



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

JUSEQUITY LAW CORPORATION

133 NEW BRIDGE ROAD
#10-03 CHINATOWN POINT
SINGAPORE 059413

Ref: CS/LAW22010876/Gqy3e2

Date: 16/11/2022

Code: L053

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SMQ 8273H	Veh. Inspected	FBP 5085P
Policy No.		Coverage (\$)	0.00
Claim No.	JEQ/210356/0721/HC.ml	Excess (\$)	0.00
Assign From	MICHELLE LIEW	Assign Date	19/10/2022

2. Vehicle Particulars & Condition

Make & Model	YAMAHA SNIPER T150	c.c	150
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3UG0740K0152800	Colour	BLUE
Odometer	22173 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	100/80-17	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	16/06/2021	Inspection Date	02/11/2022
Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------