



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SECURUS LEGAL LLC 101 CECIL STREET #14-08 TONG ENG BUILDING SINGAPORE 069533			Ref: CS/LAW22010876/Gqy3e2	
			Date: 16/11/2022	
			Code: L180	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	SMQ 8273H	Veh. Inspected	FBP 5085P
	Policy No.		Coverage (\$)	0.00
	Claim No.	TWK.SHA.0310.22.N.PIPD	Excess (\$)	0.00
	Assign From	MICHELLE LIEW	Assign Date	19/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA SNIPER T150	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH3UG0740K0152800	Colour	BLUE
	Odometer	22173 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	DUNLOP	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	100/80-17	MAXXIS	6 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/06/2021	Inspection Date	02/11/2022
	Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	