



Your Ref : 202222007815-FIRE

Date: 05th Dec 2022

Our Ref : CS4/AIS22010890/Nvy3e2

M/s Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE EP 8338E
ACCIDENT ON 30/10/2022**

Instruction was received to inspect the vehicle Reg. No. EP 8338E. The inspection was conducted on 02/11/2022 at the premises of M/s Mova Automotive Pte Ltd, Blk 1008 Bukit Merah Lane 3 #01-04/06/08, Singapore 159722.

The following vehicle information was recorded:

Registration Number	: EP 8338E
Make/Model	: Mercedes Benz GLS400 D 4Matic AMG Line Auto
Year of Registration	: 2020
Body Colour	: Grey
Chassis Number	: WDC1679232A074155
Engine Capacity	: 2925 cc
Speedometer Reading	: Not Available (Battery Melted)

The vehicle caught fire. The cause of fire probably due to electrical short circuit (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	350,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	122,217.00)
Nett Liability	S\$	<u>227,783.00</u>
		=====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MInstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.