

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010904/ANCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant: CHEAH ELEANOR @HSIEN YUN-HUNG ELEANOR

Policy No: 7220033857

Date of Loss: 17/10/2022

Nature of Claim: OD

Claim No: 0505093289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG8152A**
 Make & Model: AUDI E-TRON, SPORTBACK ADV 50 QUATTRO (A) Engine No: HIDDEN
 Reg. Date: 31/03/2022 (Man. Year: 2022) Chassis No: WAUZZZGE1NB026893
 Colour: Beige Odometer: 7668 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: S\$340,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 265/45 R21 Rear Tyre Size: 265/45 R21
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,294.00	1,931.20	9,362.80	82.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,662.00	3,232.00	2,430.00	42.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,956.00	5,163.20	11,792.80	69.55
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	15,756.00	3,963.20	11,792.80	74.85
+ GST 8.00/8.00% (S\$)	1,260.48	317.06	943.42	74.85
Nett Amount (S\$)	17,016.48	4,280.26	12,736.22	74.85

INSPECTION

Date of Assignment: 02/11/2022

Date Inspected: 01/11/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,914.00 FS	*- FS
2	1		*REAR BUMPER TRIM - CENTER	Not Necessary	580.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	1,688.00 FS	*1,350.40 FS
4	1		*REAR BUMPER DIFFUSER	Not Necessary	1,167.00 FS	*- FS
5	2		*REAR BUMPER SECURING STRIP - UPPER / LOWER	Not Necessary	386.00 FS	*- FS
6	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	152.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	71.00 FS	*- FS
8	1		*REAR BUMPER LOCKING MECHANISM - LH	Not Necessary	19.00 FS	*- FS
9	1		*REAR BUMPER CLOSING ELEMENT - LH	Not Necessary	79.00 FS	*- FS
10	1		*REAR PARKING AID SENSOR - LH	Not Necessary	292.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
12	2		*REAR WHEEL COVER - LH / RH	Necessary	726.00 FS	*580.80 FS
13	1		*REAR ALUMINIUM RIM - LH	Not Necessary	3,910.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,294.00	1,931.20
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DEACTIVATE AND REACTIVATE HIGH VOLTAGE SYSTEM FOR VEHICLE	New	480.00	480.00
3	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
4	TO RESPRAY REAR BUMPER, REAR LOWER SPOILER AND BOTH REAR WHEEL ARCH TRIMS	New	3,000.00	1,600.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,662.00	3,232.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >