

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010908/AVCE2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant:	AN QINGFENG	Policy No:	1800153613-03	
Date of Loss:	26/10/2022	Nature of Claim:	OD	Claim No: 4893942852SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8019D		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZB20862
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZGA4KA003381
Colour:	White	Odometer:	48887 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$106,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,081.00	7,409.84	15,671.16	67.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,352.00	10,457.00	9,895.00	48.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,433.00	17,866.84	25,566.16	58.86
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	43,033.00	17,466.84	25,566.16	59.41
+ GST 8.00/8.00% (S\$)	3,442.64	1,397.35	2,045.29	59.41
Nett Amount (S\$)	46,475.64	18,864.19	27,611.45	59.41

INSPECTION

Date of Assignment:	02/11/2022		
Date Inspected:	01/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,363.00 FS	*- FS
2	1		*REAR BUMPER SPOILER	Not Necessary	316.00 FS	*- FS
3	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	34.00 FS	*- FS
4	1		*REAR TAIL LIGHT - RH	Not Necessary	1,469.00 FS	*- FS
5	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	60.00 FS	*- FS
6	1		*REAR SIDE PANEL - RH	Dented	2,659.00 FS	*2,127.20 FS
7	1		*REAR PILLAR C TRIM - RH	Not Necessary	693.00 FS	*- FS
8	1		*REAR FOAM STRIPS	Necessary	153.00 FS	*122.00 FS
9	1		*PLASTIC PRIMER	Necessary	106.00 FS	*84.80 FS
10	1		*REAR FUEL TANK FLAP COVER	Not Necessary	107.00 FS	*- FS
11	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	220.00 FS	*- FS
12	1		*REAR VENT TRIM	Not Necessary	36.00 FS	*- FS
13	1		*RAER SIDE MEMBER TRIM - RH	Not Necessary	251.00 FS	*- FS
14	1		*REAR DOOR - RH	Dented	2,962.00 FS	*2,369.60 FS
15	1		*REAR OUTER DOOR SEAL - RH	Necessary	151.00 FS	*120.40 FS
16	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
18	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
19	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	98.00 FS	*- FS
20	1		*REAR DOOR CATCH - RH	Necessary	134.00 FS	*106.80 FS
21	1		*REAR INNER DOOR SEAL - RH	Not Necessary	313.00 FS	*- FS
22	1		*REAR OUTER DOOR SEAL - RH	Not Necessary	66.00 FS	*- FS
23	1		*REAR DOOR UPPER HINGE - RH UPPER	Not Necessary	49.00 FS	*- FS
24	1		*REAR DOOR UPPER HINGE - RH LOWER	Not Necessary	54.00 FS	*- FS
25	1		*REAR DOOR LOWER HINGE - RH UPPER	Not Necessary	53.00 FS	*- FS
26	1		*REAR DOOR LOWER HINGE - RH LOWER	Not Necessary	49.00 FS	*- FS
27	1		*REAR DOOR COVER - RH	Cut	238.00 FS	*190.40 FS
28	1		*REAR DOOR HANDLE BASE - RH	Repair	182.00 FS	*- FS
29	1		*REAR DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
30	1		*REAR DOOR LOCK - RH	Not Necessary	630.00 FS	*- FS
31	1		*REAR DOOR STRIKER	Not Necessary	69.00 FS	*- FS
32	1		*REAR WINDOW REGULATOR - RH	Not Necessary	302.00 FS	*- FS
33	1		*RAER WINDOW REGULATOR MOTOR	Not Necessary	308.00 FS	*- FS
34	1		*REAR DOOR PANEL - RH	Not Necessary	1,167.00 FS	*- FS
35	1		*REAR WINDOW GUIDE	Not Necessary	455.00 FS	*- FS
36	1		*REAR PILLAR B TRIM - RH	Cut	130.00 FS	*103.60 FS
37	1		*RAER WINDOW APERTURE SEAL - RH OUTER	Not Necessary	151.00 FS	*- FS
38	1		*RAER WINDOW APERTURE SEAL - RH INNER	Not Necessary	125.00 FS	*- FS
39	1		*REAR FIXED DOOR WINDOW SEAL - RH	Not Necessary	350.00 FS	*- FS
40	1		*REAR DOOR WINDOW - RH	Not Necessary	219.00 FS	*- FS
41	1		*FRONT DOOR - RH	Not Necessary	2,962.00 FS	*- FS
42	1		*FRONT DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
43	1		*FRONT DOOR COVER - RH	Not Necessary	270.00 FS	*- FS
44	1		*REAR TRYE PRESSURE DATA PLATE	Not Necessary	34.00 FS	*- FS
45	2		*REAR WHEEL COVER - LH / RH	O/S Cut / N/S Necessary	360.00 FS	*287.20 FS
46	1		*REAR PILLAR B TRIM - RH	Cut	130.00 FS	*103.60 FS
47	1		*REAR WINDOW GUIDE	Not Necessary	459.00 FS	*- FS
48	1		*RAER WINDOW APERTURE SEAL - RH OUTER	Not Necessary	151.00 FS	*- FS
49	1		*REAR WINDOW APERTURE SEAL - RH INNER	Not Necessary	125.00 FS	*- FS
50	1		*REAR ALUMINIUM RIM	Cut	1,002.00 FS	*801.60 FS
51	1		*RAER ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
53	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
54	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
55	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
56	1		*SUNDRIES	Necessary	600.00 FS	*89.60 FS
57	8		*CLIP FOR GASKET (Supplementary)	Necessary	22.00 FS	*17.28 FS
58	1		*CLIP FOR GASKET (Supplementary)	Necessary	8.00 FS	*6.32 FS
59	2		*2 PK PLASTIC ADHESIVE (Supplementary)	Necessary	117.00 FS	*92.96 FS
60	1		*APPLICATOR (Supplementary)	Necessary	9.00 FS	*6.48 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	23,081.00 7,409.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
4	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES	New	400.00	0.00
5	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	3,500.00
6	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	280.00
9	TO RESPRAY REAR BUMPER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HINGES, DOOR HANDLE, RHS REAR FENDER, ROOF CHANEL, RHS C-PILLAR TRIM BOARD, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	8,000.00	2,725.00
Gross Labour Cost (\$\$)			20,352.00	10,457.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >