

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0938/2022/EQ
DATE : 28-Oct-22
WIP : 47659

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR AN QINGFENG
ADDRESS : BLK 261B PUNGGOL WAY
#14-333
SINGAPORE 822261
TELEPHONE : HP +65 81182979
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800153613-03
VEHICLE NO : **SMG 8019 D**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 31/12/2018
ENGINE NO : CHZ B20862
CHASSIS NO : WAUZZZGA4KA003381
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-22
PLACE OF ACCIDENT : PUNGGOL WAY, SINGAPORE 821303

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 8019 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID	S/N \$	280.00	✓
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00 180	
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
5	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N \$	400.00	X.
TOTAL LABOUR CHARGES		:	\$ 4,680.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 8019 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW REAR BUMPER, RHS REAR DOOR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	3500.
7	TO RESPRAY REAR BUMPER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HINGES, DOOR HANDLE, RHS REAR FENDER, ROOF CHANNEL, RHS C-PILLAR TRIM BOARD, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING.	\$ 8,000.00	2725. 2475. Handle 100 Fuel/Lab: 150 250
8	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 20,352.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8019 D

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
1	REAR BUMPER <i>Repk</i>	1	\$	1,363.00	+
2	REAR BUMPER SPOILER <i>Not on</i>	1	\$	316.00	+
3	REAR BUMPER REFLECTOR - RH <i>new</i>	1	\$	34.00	+
4	REAR TAIL LIGHT - RH <i>new</i>	1	\$	1,469.00	+
5	REAR BUMPER GUIDE SECTION - RH <i>new</i>	1	\$	60.00	+
6	REAR SIDE PANEL - RH <i>Dented</i>	1	\$	2,659.00	✓
7	REAR PILLAR C TRIM - RH <i>new</i>	1	\$	693.00	+
8	REAR FOAM STRIPS <i>?</i>	1	\$	153.00	?
9	PLASTIC PRIMER <i>?</i>	1	\$	106.00	?
10	REAR FUEL TANK FLAP COVER <i>new</i>	1	\$	107.00	+
11	REAR WHEEL HOUSING LINER - RH <i>new</i>	1	\$	220.00	+
12	REAR VENT TRIM <i>Not on</i>	1	\$	36.00	+
13	REAR SIDE MEMBER TRIM - RH <i>new</i>	1	\$	251.00	+
14	REAR DOOR - RH <i>Dented</i>	1	\$	2,962.00	✓
15	REAR OUTER DOOR SEAL - RH <i>new</i>	1	\$	151.00	✓
16	BONDING AGENT <i>?</i>	1	\$	51.00	?
17	CLEANING SOLUTION <i>?</i>	1	\$	74.00	?
18	APPLICATOR <i>?</i>	1	\$	9.00	?
19	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$	98.00	+
20	REAR DOOR CATCH - RH <i>?</i>	1	\$	134.00	?
SUB TOTAL SPARE PARTS			\$	10,946.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8019 D

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR INNER DOOR SEAL - RH <i>not in</i>	1	\$	313.00	+
22	REAR OUTER DOOR SEAL - RH <i>not in</i>	1	\$	66.00	+
23	REAR DOOR UPPER HINGE - RH UPPER	1	\$	49.00	+
24	REAR DOOR UPPER HINGE - RH LOWER	1	\$	54.00	+
25	REAR DOOR LOWER HINGE - RH UPPER	1	\$	53.00	+
26	REAR DOOR LOWER HINGE - RH LOWER	1	\$	49.00	+
27	REAR DOOR COVER - RH <i>cut</i>	1	\$	238.00	✓
28	REAR DOOR HANDLE BASE - RH <i>Regis</i>	1	\$	182.00	+
29	REAR DOOR BOWDEN CABLE <i>not in</i>	1	\$	58.00	+
30	REAR DOOR LOCK - RH <i>not in</i>	1	\$	630.00	+
31	REAR DOOR STRIKER	1	\$	69.00	+
32	REAR WINDOW REGULATOR - RH ?	1	\$	302.00	?
33	REAR WINDOW REGULATOR MOTOR <i>not in</i>	1	\$	308.00	+
34	REAR DOOR PANEL - RH <i>not in</i>	1	\$	1,167.00	+
35	REAR WINDOW GUIDE ?	1	\$	455.00	?
36	REAR PILLAR B TRIM - RH <i>cut</i>	1	\$	130.00	✓
37	REAR WINDOW APERTURE SEAL - RH OUTER <i>not in</i>	1	\$	151.00	+
38	REAR WINDOW APERTURE SEAL - RH INNER	1	\$	125.00	+
39	REAR FIXED DOOR WINDOW SEAL - RH <i>not in</i>	1	\$	350.00	+
40	REAR DOOR WINDOW - RH <i>not in</i>	1	\$	219.00	+
SUB TOTAL SPARE PARTS		:	\$	4,968.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 8019 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT DOOR - RH	1	\$ 2,962.00	X
42	FRONT DOOR CATCH - RH	1	\$ 134.00	X
43	FRONT DOOR COVER - RH	1	\$ 270.00	X
44	REAR TYRE PRESSURE DATA PLATE	1	\$ 34.00	+
45	REAR WHEEL COVER - LH / RH	2	\$ 360.00	✓
46	REAR PILLAR B TRIM - RH	1	\$ 130.00	✓
47	REAR WINDOW GUIDE	1	\$ 459.00	X
48	REAR WINDOW APERTURE SEAL - RH OUTER	1	\$ 151.00	+
49	REAR WINDOW APERTURE SEAL - RH INNER	1	\$ 125.00	+
50	REAR ALUMINIUM RIM	1	\$ 1,002.00	✓
51	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	+
52	ACRYLIC SEALANT	S/N	\$ 180.00	✓
53	CAVITY WAX	S/N	\$ 140.00	✓
54	STONE CHIP	S/N	\$ 180.00	✓
55	METAL FILLER POWDER	S/N	\$ 280.00	✓
56	SUNDRIES		\$ 600.00	?
TOTAL SPARE PARTS		:	\$ 22,925.00	
TOTAL LABOUR CHARGES		:	\$ 20,352.00	
GRAND TOTAL		:	\$ 43,277.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *01/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 14 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKk to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT