


Section A - Accident Details

Registration Number	SHB5413D
Case Reference Number	TAX/10/22/2090
Registration Date	30/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SHANMUGAVELU S/O RAZANGAM
Type of Accident	Head to Rear
Accident Date and Time	29/10/2022 10:15 AM
Accident Reported Date and Time	31/10/2022 9:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	FRONT AND REAR PORTION
Prepared Date and Time	31/10/2022 1:10 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,228.00	\$700.00
Total Spray Cost	\$3,368.00	\$950.00
Total Spare Part Cost	\$23,505.03	\$7,696.91
Total Other Cost	\$600.00	(\$1,796.91)
TOTAL COST	\$29,701.03	\$7,550.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	7.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	07/11/2022 9:48 AM	07/11/2022 9:33 AM
Signature		
Remarks	Initial 10 days / sup 2 days / total 12days	LUMP SUM REPAIR / RESURVEY AFTER REPAIR

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0015	Invoice Number	
Quotation Date	06.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,014.00	\$200.00
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
TO REPAIR REAR END PANEL	\$200.00	\$100.00
Total Labour	\$2,228.00	\$700.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$200.00	\$150.00
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$100.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT HOOD	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$3,368.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$1,876.91)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$600.00	(\$1,796.91)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$560.30	25.00	\$420.23	Replace	Replace

✓

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/12/2022

User ID : PohSuan

	52115470 50	SUPPORT, FR BUMPER RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	52116470 50	SUPPORT, FR BUMPER LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	52127479 07	COVER, FR BUMPER RH	0.00	\$31.80	0.00	\$0.00	Replace	Not Given	X
	52128479 06	COVER, FR BUMPER LH	0.00	\$31.80	0.00	\$0.00	Replace	Not Given	X
	52114471 90	BRACKET, FR BUMPER	0.00	\$111.80	0.00	\$0.00	Replace	Not Given	X
		NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	√
		NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	√
	52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$773.90	0.00	\$0.00	Replace	Check	X
	52611471 40	ABSORBER, FR BUMPER	0.00	\$85.90	0.00	\$0.00	Replace	Check	X
	52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given	X
	52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$129.90	0.00	\$0.00	Replace	Not Given	X
	52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$265.90	0.00	\$0.00	Replace	Not Given	X
	52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$143.60	0.00	\$0.00	Replace	Not Given	X
	53395470 40	SEAL, HOOD TO FR END	0.00	\$55.80	0.00	\$0.00	Replace	Not Given	X
	75310470 60	EMBLEM ASSY FRONT	1.00	\$98.70	25.00	\$74.03	Replace	Replace	√
	53112472 40	GRILLE, RADIATOR	0.00	\$183.90	0.00	\$0.00	Replace	Not Given	X
	53101470 80	GRILLE SUB-ASSY	1.00	\$374.40	25.00	\$280.80	Replace	Replace	√
	52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
	52535500 60	RETAINER, FR BUMPER, LH & RH	0.00	\$9.50	0.00	\$0.00	Replace	Not Given	X
	51420470 30	COVER ASSY, ENGINE	0.00	\$201.00	0.00	\$0.00	Replace	Not Given	X
	51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$511.20	0.00	\$0.00	Replace	Not Given	X
	51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	51444470 10	COVER, ENGINE UNDER SIDE LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given	X
	81210470 20	LAMP ASSY, FOG, RH	0.00	\$1,029.90	0.00	\$0.00	Replace	Not Given	X
	81220470 20	LAMP ASSY, FOG, LH	0.00	\$1,029.90	0.00	\$0.00	Replace	Not Given	X
	81185476 91	UNIT , HEADLAMP , LH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace	√
	81145476 91	UNIT , HEADLAMP , RH	1.00	\$2,852.40	10.00	\$2,567.16	Replace	Replace	√
	81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$1,039.90	0.00	\$0.00	Replace	Not Given	X
	81016476 90	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$1,039.90	0.00	\$0.00	Replace	Not Given	X
	53301471 10	HOOD SUB-ASSY	0.00	\$1,066.30	0.00	\$0.00	Replace	Not Given	X
	53410471 30	HINGE ASSY, HOOD, RH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given	X
	53420471 30	HINGE ASSY, HOOD, LH	0.00	\$63.70	0.00	\$0.00	Replace	Not Given	X
	53205479 00	SUPPORT S/A UPPER,	0.00	\$408.50	0.00	\$0.00	Replace	Not Given	X
	53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
	53801470 80	FENDER SUB-ASSY, FR , RH	0.00	\$1,060.70	0.00	\$0.00	Replace	Not Given	X
	75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
	53875470 70	LINER, FR FENDER, RH	0.00	\$223.50	0.00	\$0.00	Replace	Not Given	X
	53802471 00	FENDER SUB-ASSY, FR , LH	0.00	\$1,060.70	0.00	\$0.00	Replace	Not Given	X
	75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
	53876471 10	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given	X
	52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace	√

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 12/12/2022

User ID : PohSuan

	5202347030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
	5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
	5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
	5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace	√
	5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	Replace	√
	5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	Replace	√
	5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	5257647040	RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	5259147050	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	X
	5259247040	SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	X
	5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace	√
	5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√
	5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
	5256647900	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	X
	5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.53	Replace	Replace	√
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	X
	9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
	8155147281	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	8158147010	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	8159147010	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X
	5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
	6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
	6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	1.00	\$1,238.40	100.00	\$0.00	Replace	Repair	R
	6788147050	TAIL GATE WEATHERSTRIP, BACK DOOR	0.00	\$402.50	0.00	\$0.00	Replace	Not Given	X
	7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$992.30	100.00	\$0.00	Replace	Repair	R
	7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
	7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	√
		STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	√
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
	5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	6935047050	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$505.50	0.00	\$0.00	Replace	Not Given	X
	6932147010	TAIL GATE LOCK COVER , BACK DOOR	1.00	\$32.70	25.00	\$24.53	Replace	Replace	√
Total				\$27,797.60		\$7,057.52			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5211447190	BRACKET, FR BUMPER	1.00	\$111.80	25.00	\$83.85	Replace	Replace

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/12/2022

User ID : PohSuan

		52611471 40	ABSORBER, FR BUMPER	1.00	\$85.90	25.00	\$64.43	Replace	Replace
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	Replace
		66259470 10	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	Replace
		17753370 10	INLET, AIR CLEANER, NO 3	1.00	\$45.60	25.00	\$34.20	Replace	Replace
Total					852.50		639.39		

√
√
√
√

7,696.91
+ 700.00 L/S \$7,550/-
+ 1030.00
9,426.91
-20%
7,541.53