

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 06/12/2022

User ID : PohSuan

Section A - Accident Details

Registration Number	SHD6012K
Case Reference Number	TAX/10/22/2095
Registration Date	19/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	ANG HIN LENG
Type of Accident	Side Swipe
Accident Date and Time	29/10/2022 4:30 PM
Accident Reported Date and Time	31/10/2022 1:59 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116708
Special Instruction to ARC, if any	TP/LEFT PORTION
Prepared Date and Time	31/10/2022 3:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$2,628.00	\$1,170.00
Total Spare Part Cost	\$7,261.74	\$104.33
Total Other Cost	\$840.00	(\$374.33)
TOTAL COST	\$11,743.74	\$1,500.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	6.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	02/11/2022 8:52 AM	01/11/2022 4:51 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER REPAIR

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2212-0007	Invoice Number	
Quotation Date	05.12.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$70.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,628.00	\$1,170.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$374.33)
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
Total Other Costs	\$840.00	(\$374.33)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$560.30	100.00	\$0.00	Replace	Repair
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$86.20	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		5215947913	COVER, RR BUMPER ASSY	0.00	\$478.90	0.00	\$0.00	Replace	Not Given
		5380247100	FENDER SUB-ASSY, FR , LH	1.00	\$1,060.70	100.00	\$0.00	Replace	Repair
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	Replace
		5387647110	LINER, FR FENDER, LH	0.00	\$219.10	0.00	\$0.00	Replace	Not Given

R
X nn
Xnn
X nn
R
√ nec
X nn

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 06/12/2022

User ID : PohSuan

		7586047900	MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$649.10	100.00	\$0.00	Replace	Repair	R
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	100.00	\$0.00	Replace	Repair	R
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√ nec
		6872012151	HINGE ASSY, FRONT DOOR , UPPER LH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X nn
		6874012120	HINGE ASSY, FRONT DOOR , LOWER LH	0.00	\$120.00	0.00	\$0.00	Replace	Not Given	X nn
		6861047040	CHECK ASSY, FRONT DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X nn
		8794047440	MIRROR ASSY, OUTER REAR VIEW , LH	0.00	\$1,454.40	0.00	\$0.00	Replace	Not Given	X nn
		8794547060A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	100.00	\$0.00	Replace	Repair	R
		6700447210	PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
		6876020122	HINGE ASSY, REAR DOOR , UPPER LH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X nn
		6878052031	HINGE ASSY, REAR DOOR , LOWER LH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X nn
		6863047050	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X nn
		6160247160	PANEL SUB-ASSY, FENDER REAR LH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
Total					\$9,328.20		\$104.33			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	104.33	
+	600.00	L/S \$1,500/-
+	1170.00	
	1,874.33	
	-20%	
	1,499.46	