

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 19 Jun 2023

Preliminary Advice

Insured Vehicle No	: SLV3948M	Accident Date	: 28/10/2022
TP Vehicle No	: SMH678Z	Assignment Date	: 02/11/2022
Make	: MERCEDES-BENZ E200 AVG	Est. Duration of Repair	: 4
Date of Inspection	: 21/12/2022		
Inspection At	: CHENG HOE MOTOR SERVICE		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,624.10
Revised Amount	:S\$	6,000.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	118,000.00
COE / PARF Rebate	:S\$	68,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	49,049.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .