



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG		Ref: CC4/ASM22010928/Spa3q2 Date: 19/04/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLP 9664Z	Veh. Inspected	SNF 9805M
Policy No.	GA513784	Coverage (\$)	0.00
Claim No.	S2M04DO9	Excess (\$)	0.00
Assign From		Assign Date	01/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	NHP1707265954	Colour	WHITE
Odometer	28331 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	6 mm
L/H Front Tyre	205/50 R16	FALKEN	6 mm
R/H Rear Tyre	205/50 R16	FALKEN	6 mm
L/H Rear Tyre	205/50 R16	FALKEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	27/10/2022	Inspection Date	01/11/2022
Survey held at	RS GARAGE SERVICES PTE LTD BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	