

Chassis: NHP1707265954

RS GARAGE SERVICES PTE LTD

To : AXA Insurance Pte Ltd
 Vehic : SNF 9805 M
 Make : Toyota Sienta
 Date : 27-Oct-2022

Date : 02-Nov-2022

Page No : 1

S/n	Description	Unit	Price	Surveyor
1	Tailgate		1799.50	1500
2	Windscreen Glass Moulding		225.50	200 180
3	Tailgate "Hybrid" Emblem		68.00	/
4	Tailgate Inner Trim		566.50	300
5	Tailgate Inner Lock		425.50	350
6	Tailgate Center Garnish		385.50	150
7	Tailgate Weather Stripe		501.50	300
8	Tailgate Lamp RH		445.50	300
9	Tailgate Lamp LH		445.50	300
10	Rear Bumper		1520.30	1200
11	Rear Bumper Center Garnish Left		387.60	300
12	Rear Bumper Center Garnish Right		387.60	300
13	Rear Bumper Center Garnish		425.50	300
14	Rear Bumper Reflector LH		112.50	X
15	Rear Bumper Reflector RH		112.50	X
16	Rear Bumper Towing Cap		55.00	X
17	Rear Bumper Side Retainer LH		112.50	90
18	Rear Bumper Side Retainer RH		112.50	90
19	Rear End Panel		955.50	800
20	Rear End Panel Top Garnish		225.50	200
21	Rear Center Towing Panel		375.50	XR
22	Spare Tire Panel		975.50	750
23	Rear Fender RH Inner Trime		675.50	400
24	Rear Fender LH Inner Trime		675.50	400
25	Rear End Panel		755.80	X
26	Rear End Panel Top Garnish		386.70	X
27	Tail Lamp RH		615.50	300
28	Tail Lamp LH		615.50	X
29	Tail Lamp Lower Bracket RH		185.50	/
30	Tail Lamp Lower Bracket LH		185.50	/
31	Spare Tire Top Panel Board		285.50	X
32	Number Plate Lights LH/RH	85	110.00	/
33	Wiper Motor		583.50	550
34	Rear Exhaust Assembly		975.50	XR
			16671.00	9609
		Less 25%	12503.25	2402
	Special Nett			
35	Windscreen Sealant		150.00	60 NEC
36	Winscreen Primer		100.00	X NV
37	Bumper Clips one set		100.00	50 NEC
38	End Panel Sealant		100.00	60 NEC
39	Spare Tyre Panel Sealant		150.00	60 NEC
40	Reverse Sensors		400.00	1200 DM
			1000.00	430

Damage
 Dent/Buc
 NEC
 NEC
 Dent
 Dent
 BR
 Torn
 BR
 BR
 BR
 Buc
 NEC
 NEC
 Buc
 NV
 NV
 NV
 BR
 BR
 Buc
 Dent
 Buc
 Buc
 BR
 BR
 Repeat
 Repeat
 BR
 NV
 BR
 BR
 NV
 NV
 BR
 Dent
 Dent

Labour				
41	Panel Beat, Repair n Replacement		1400.00	950
42	Windscreen R n R		200.00	120
43	Reverse Sensors R n R		200.00	60
44	Check Wiring		100.00	30
45	Exhaust Assembly R & R		180.00	60
46	Spray Paint Affected Area		1400.00	800
47	Hydrid Battery R & R		250.00	X
48	Resetting of Fault Code		120.00	X
		Total	3850.00	
		Grand Total	17353.25	9657

20% - 1931

Final = 7726

~ 7750

1 r fan 3/11/22
 90097659
 L/S 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: