



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010934/Kvy3m4 Date: 29/11/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 558M	Veh. Inspected	SDK 9198Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS22/1280	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	01/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	-	
Chassis No.	MR053REH104527428	Colour	METALLIC GREY	
Odometer	50040 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	7 mm	
L/H Front Tyre	205/55 R16	DUNLOP	7 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	7 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2022	Inspection Date	07/11/2022	
Survey held at	1 SIN MING INDUSTRIAL SECTOR C #01-135			
Repairer	A T AUTO CONSULTANT			
5a. Remarks				
A)REGISTRATION DATE: 11 MARCH 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	