

A/T AUTO CONSULTANT

Bik 13 Tuck Whye Lane #05-650 Singapore 680113
HP: 838 8989 EMAIL: atautoconsultant@gmail.com
Co. Reg. No.: 53368526E

Date of Estimate: 01.11.2022
Vehicle No: SDK9198Z
Owner: LEE TECK CHUAN
Date of Accident: 30.11.2022
Make & Model: TOYOTA COROLLA ALTIS 1.6L CVT
Chassis No: MR053REH104527428

Not Notified
L1 Rep &
Resurvey After Painting
2 days

ESTIMATE FOR ACCIDENT VEHICLE NOS SDK9198Z

PARTS

- | | |
|---|-----------------------------------|
| 1 | 1 Rear bumper |
| 2 | 2 Rear bumper side retainer RH/LH |
| 3 | 1 Bootlid |

also @

\$83.00

Part	\$840.00	✓
	\$166.00	✓
Part	\$1,100.00	X
SUB TOTAL	\$2,106.00	
LESS 25%	\$526.50	
DISCOUNTED SUB TOTAL	\$1,579.50	

S.NETT

- | | |
|---|------------------------|
| 1 | 1set Rear bumper clips |
| 2 | 1set Reverse sensor |

Part	50.00	✓
Part	320.00	2000
SUB TOTAL	\$370.00	

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Apply undercoating to above affected areas |
| 5 | R/R bootlid component |

	\$600.00	2000
	\$800.00	2200
	\$100.00	100
Part	\$180.00	X
Part	\$200.00	X
SUB TOTAL (LABOUR)	\$1,880.00	

SUB TOTAL (LABOUR)

SUN TOTAL (S.NETT)

\$370.00

SUB TOTAL (PARTS)

\$1,579.50

SUB TOTAL (LABOUR)

\$1,880.00

ESTIMATED GRAND TOTAL

\$3,459.50

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: