



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 5737896

HP: 93911482

3119.92

60.00

1220.00

4399.92

20%

Estimation

Date:

Vehicle:

Make / Model:

Chassis No:

1/11/2022

SND4002G

TOYOTA PRIUS

LIBERTY

Rasue

Hy 90010068

5 days

4/5

02/11/22 @ 1435

Resue after repair

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT DOOR RH <i>bt</i>	1	\$ 1,359.00	\$ 1,359.00 <i>1258</i>
2	FRONT DOOR INNER LOCK RH <i>cut</i>	1	\$ 312.00	\$ 312.00 <i>✓</i>
3	FRONT DOOR OUTER MOULDING RH <i>de</i>	1	\$ 112.00	\$ 112.00 <i>92</i>
4	FRONT DOOR FRAME BLACK STICKER <i>m</i>	1	\$ 89.00	\$ 89.00 <i>✓</i>
5	FRONT DOOR FRAME GARNISH RH <i>Xnn</i>	1	\$ 159.00	\$ 159.00 <i>X</i>
6	FRONT DOOR OUTER HANDLE RH <i>sea</i>	1	\$ 321.00	\$ 321.00 <i>202.65</i>
7	FRONT DOOR WETHETRSTRIP RH <i>m</i>	1	\$ 212.00	\$ 212.00 <i>✓</i>
8	FRONT DOOR INNER TRIM BOARD RH <i>?cm</i>	1	\$ 425.00	\$ 425.00 <i>✓</i>
9	FRONT DOOR POWER WINDOW REGULATOR RH <i>?b</i>	1	\$ 412.00	\$ 412.00 <i>278.30</i>
10	FRONT DOOR POWER WINDOW MOTOR RH <i>?Xnn</i>	1	\$ 698.00	\$ 698.00 <i>X</i>
11	SIDE SKIRTING RH <i>Xnn</i>	1	\$ 1,025.00	\$ 1,025.00 <i>X</i>
12	DOOR CENTRE PILLAR RH <i>refur</i>	1	\$ 687.00	\$ 687.00 <i>XR</i>
13	REAR DOOR RH <i>bt</i>	1	\$ 1,359.00	\$ 1,359.00 <i>1201.95</i>
14	REAR DOOR HINGES RH <i>top? Xnn</i>	1 <i>X</i>	\$ 65.00	\$ 130.00 <i>X</i>
15	REAR DOOR OUTER MOULDING RH <i>Xnn</i>	1	\$ 159.00	\$ 159.00 <i>X</i>
16	REAR DOOR FRAME GARNISH RH <i>sea Xnn</i>	1	\$ 159.00	\$ 159.00 <i>X</i>
17	REAR DOOR FRAME BLACK STICKER RH <i>m</i>	1	\$ 89.00	\$ 89.00 <i>✓</i>
	TOTAL PART			\$ - <i>4159.90</i>
	LIST DOWN	25%		\$ 1,978.25 <i>252</i>
	AFTER LIST DOWN			\$ 5,934.75 <i>3119.92</i>
	SPEICAL NETT			
1	FRONT DOOR INNER TRIM CLIPS <i>m</i>	1	\$ 50.00	\$ 50.00 <i>303</i>
2	REAR DOOR INNER TRIM CLIPS <i>m</i>	1	\$ 50.00	\$ 50.00 <i>303/60</i>
	TOTAL AMOUNT			\$ 100.00
	LABOUR			
1	CHECK WIRING <i>Xnn</i>	1	\$ 100.00	\$ 100.00 <i>X</i>
2	REMOVE AND REFIR FRT DOOR MECHANISM	1	\$ 150.00	\$ 150.00 <i>60</i>
3	REMOVE AND REFIR REAR DOOR MECHANISM	1	\$ 150.00	\$ 150.00 <i>60</i>
4	PANEL BEAT EFFECTED AREAS	1	\$ 800.00	\$ 800.00 <i>500</i>
5	RESPAINT EFFECTED AREAS	1	\$ 800.00	\$ 800.00 <i>600</i>
	TOTAL AMOUNT			\$ 2,000.00 <i>1220</i>
	Parts Replacement Amount			\$ 6,340.00
	Total Amount for Labour			\$ 1,860.00
	Total Amount			\$ 8,200.00
	Acknowledged by Repairer			
	Signature:			
	Date:			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the repair painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company