

ASS. REC. BY:

REF:

Tm1 / TP

Aspire 2

A314

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S1109299E

Yr Regn:

03, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pro

C.C

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU80307981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Wadi 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Wadi

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

29/10/22

D.O.I.

1/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2 / 174

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Bootlid jammed, Battery flat.

May submit as TP report as Tm1 said insured not under them

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

F. m. s

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E*Not Attached
1/12/22***AAD2210-108**

Vehicle No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 NOV 2022**SHD9299E**

201603575K

TOYOTA

PRIUS

29/10/2022

GBE1137H / TOKIO MARINE

17/5/2019

PART**LIST**

1 COVER, REAR BUMPER	\$	<i>RH/CM</i> 442.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>RH</i> 332.70	✓
1 COVER, REAR BUMPER, LOWER	\$	<i>RH</i> 15.40	✓
1 GUARD, REAR BUMPER, CENTER	\$	<i>RH</i> 576.30	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>DRY</i> 116.50	✓
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>DRY</i> 117.70	✓
1 FILLER, REAR BUMPER EXTENSION, RH	\$	<i>NG/CM</i> 123.70	✓
1 FILLER, REAR BUMPER EXTENSION, LH	\$	<i>SM</i> 123.70	X
1 PANEL SUB-ASSY, BACK DOOR	\$	<i>RH</i> 1,147.80	✓
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>CM</i> 925.60	✓
1 BOARD ASSY, BACK DOOR TRIM	\$	259.20	?
1 WEATHERSTRIP, BACK DOOR	\$	372.30	?
1 BOARD, BACK DOOR TRIM	\$	225.20	?
1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	443.30	?
1 LENS AND BODY, REAR LAMP, LH (LOWER)	\$	502.00	?
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	<i>CM</i> 443.30	✓
1 LENS AND BODY, REAR LAMP, RH (LOWER)	\$	502.00	?
1 BOX, DECK FLOOR, RH	\$	<i>SM</i> 313.60	X
1 BOX, DECK FLOOR, LH	\$	<i>SM</i> 313.00	X
1 BOARD, REAR FLOOR, NO.1	\$	<i>SM</i> 519.00	X
1 BOX, DECK FLOOR, REAR	\$	<i>SM</i> 105.80	X
1 PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>RH</i> 355.90	X
1 PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>SM</i> 355.90	X
1 COVER, FLOOR UNDER, NO.1 LH	\$	175.10	?
1 COVER, FLOOR UNDER, NO.2 RH	\$	241.90	?
1 COVER, REAR FLOOR CTR	\$	229.90	?
1 COVER, DECK TRIM, REAR	\$	<i>SM</i> 126.70	X
1 PAN, REAR FLOOR	\$	<i>SM</i> 583.40	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

AAD2210-108

1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30	?
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	<i>Tr</i> 467.00	✓
1	SWITCH ASSY, BACK DOOR OPENER	\$	<i>Sm</i> 179.10	X
1	SEAL, REAR BUMPER SIDE, LH	\$	<i>Sm</i> 88.50	X
1	DUCT ASSY, QUARTER VENT, LH	\$	<i>Sm</i> 67.00	X
1	SEAL, REAR BUMPER SIDE, RH	\$	<i>Sm</i> 88.50	X
1	DUCT ASSY, QUARTER VENT, RH	\$	<i>Sm</i> 67.00	X
1	SPOILER, SUB ASSY, REAR	\$	1,575.40	?
1	GLASS, BACK WINDOW FIX	\$	<i>Shatterd</i> 761.40	✓
1	DAM, BACK DOOR GLASS ADHESIVE, NO.2	\$	<i>Re</i> 28.90	—
1	STAY ASSY, BACK DOOR, LH	\$	<i>Sm</i> 242.50	X
1	STAY ASSY, BACK DOOR, RH	\$	<i>Sm</i> 242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>R</i> 61.00	X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>R</i> 61.00	X
1	REAR TAILGATE TOYOTA LOGO	\$	<i>Re</i> 47.90	—
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>Re</i> 54.60	—
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>Re</i> 54.60	—
1	COVER, FRONT BUMPER	\$	<i>Ben</i> 516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	<i>Sm</i> 103.40	X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60	?
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10	?
1	ABSORBER, FRONT BUMPER, LOWER	\$	<i>Sm</i> 132.70	X
1	ABSORBER, FRONT BUMPER ENERGY	\$	<i>Sm</i> 79.60	X
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	<i>Sm</i> 80.10	X
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	<i>Sm</i> 82.30	X
1	EXTENSION, FRONT BUMPER, RH	\$	<i>Sm</i> 120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	<i>Sm</i> 120.10	X
1	COVER, FRONT BUMPER HOLE, RH	\$	<i>Sm</i> 29.30	X
1	UNIT ASSY, HEADLAMP, LH	\$	2,637.60	?
1	UNIT ASSY, HEADLAMP, RH	\$	2,637.60	?
1	GRILLE SUB-ASSY, RADIATOR	\$	<i>CM</i> 346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	170.10	?
1	EMBLEM ASSY, RADIATOR GRILLE	\$	<i>Not</i> 90.80	✓
1	HOOD SUB-ASSY	\$	<i>R</i> 983.10	X
1	HINGE ASSY, HOOD, LH	\$	<i>R</i> 58.90	X
1	HINGE ASSY, HOOD, RH	\$	<i>R</i> 58.90	X
1	BRACE, HOOD LOCK SUPPORT	\$	<i>R</i> 78.30	X
1	INSULATOR, HOOD	\$	<i>Sm</i> 410.90	X

Trans-cab Auto Services Pte Ltd

AAD2210-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

1 LOCK ASSY, HOOD	\$	11	135.00	X
1 SEAL, HOOD TO FRONT END PANEL	\$	11	51.60	X
1 JAR ASSY, WINDSHIELD WASHER	\$	1m	219.10	X
1 CONDENSER ASSY, COOLER	\$	1m	1,783.20	X
1 CLEANER ASSY, AIR	\$	1m	1,147.00	X
1 BRACKET, HEADLAMP, LH	\$	1m	34.80	X
1 BRACKET, HEADLAMP, RH	\$	1m	34.80	X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	1m	59.30	X
1 BRACKET, FRONT BUMPER SIDE, RH	\$	1m	59.30	X

TOTAL	\$	27,949.30
25%	\$	6,987.33
	\$	20,961.98

Special Nett

1SET PARKING AID	\$	1m	700.00	220sn
1SET REAR BUMPER CLIP	\$	1m	95.00	60sn
2 WINDSCREEN SEALANT	\$	1m	150.00	80sn
1 WINDSCREEN MOULDING	\$	1m	200.00	—
1 WINDSCREEN INNER SPONGE SEAL	\$	1m	130.00	30sn
1 REAR TAILGATE STICKER "Trans-Cab"	\$	1m	80.00	30sn
1 REAR TAILGATE STICKER "6555-3333"	\$	1m	80.00	30sn
1 REAR BUMPER PROTECTOR	\$	1m	180.00	30sn
2 SEAM SEALANT	\$	1m	250.00	X
1SET REAR BUMPER RETAINER CLIP	\$	1m	85.00	X
1 REAR NUMBER PLATE WITH HOLDER	\$	1m	140.00	45sn
1SET TAILLAMP LOWER CLIP	\$	1m	55.00	X
1SET TAILLAMP UPPER CLIP	\$	1m	55.00	X
1 END PANEL TRIM CLIP	\$		65.00	?
1 REAR SPOILER CLIP	\$		70.00	?
1SET BUMPER CLIP FRT	\$	1m	95.00	60sn
1 FRONT NUMBER PLATE WITH MOULDING	\$	1m	200.00	45sn
1SET CLIP, FRONT FENDER LINER	\$	1m	85.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	1m	85.00	X
1 HOOD INSULATOR CLIP	\$	1m	55.00	X

Trans-cab Auto Services Pte Ltd

AAD2210-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

TOTAL	\$	2,855.00
-------	----	----------

TOTAL PARTS	\$	23,816.98
-------------	----	-----------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	1801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	8001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	Repair X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	601
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	NA X
To check steering geometry and computer wheel alignment	\$	220.00	NA X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,800.00	11001
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	401

Trans-cab Auto Services Pte Ltd

AAD2210-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9299E

To transfer of luggage floor panel fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 220.00 X

To replace, refix and top up coolant for radiator

\$ *nn* 170.00 X**TOTAL** \$ **9,050.00****Over All Total** \$ **32,866.98****(LUMP SUM) Repair Days**~~14 DAYS~~*6 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary works must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHD9299E

Vehicle to be Exported:

No

Intended Deregistration Date:

01 Nov 2022

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS SDR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2C08754

Chassis No.:

JTDKB3FU803079981

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

17 May 2019

First Registration Date:

17 May 2019

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 May 2027

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

16 May 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$22,309.00

COE Rebate Amount:

\$12,661.00

Total Rebate Amount:

\$23,346.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Nov 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/10/2022 17:28 (SGT)
Reported by	Driver
Date of Accident	29/10/2022 19:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BUKIT PANJANG ROAD BEFORE TURNING RIGHT TO BUKIT PANJANG RING ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9299E
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	TOH ALBERT
NRIC No	SXXXX270B
Date Of Birth	09/11/1968

Occupation	Outdoor
Date Of Driving Pass	18/04/1996
Driving experience	26 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91053427
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	HDB Bukit Batok, 315 Bukit Batok Street 32 #02-105
Address complement	-
Postcode	650315
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	RELIEF
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	P1
Gender	Female

PASSENGER 2

Name	P2
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Hong Kah North Neighbourhood Police Post
Police Station Phone No	(Phone) +65-18005679999
Alt. Police Station Phone No	(Fax) +65-65652508
Police Station Address	Blk 370 Bukit Batok Street 31 #01-201 Singapore 650370
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
---	-----

 Accident report SA1D22AV000C

Was there any video captured by Car Camera?
Reasons for not uploading a video of the accident

Yes
WITH TRANSCAB

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1137H
Vehicle Manufacturer	Nissan
Vehicle Model	Nv350
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	ADABALA DIVAKAR
Passport No/FIN	GXXXX286R
Contact Number	(Phone) +65-89464338
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFW8108D
Vehicle Manufacturer	Mini
Vehicle Model	Cooper
Vehicle Variant	-
Vehicle Colour	Green
Vehicle Category	Private car
Name of Driver	JEFF TAY
Contact Number	(Phone) +65-82828008
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

PASSENGER 1


Name	P1
Gender	Female

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TOH ALBERT
Gender	Male
Phone No	(Phone) +65-91053427
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SHD9299E
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

ACCIDENT DIAGRAM



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
ANG QI HAO, VICTOR

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: