

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BARRELS N LITRES PTE LTD
13 JOO KOON CRESCENT
SINGAPORE 629021

Contact : 93832360, 90281850

TP Budget Direct.
Veron.

TAX INVOICE

Repair Code : CLM15326

Date in : 31/10/2022

Vehicle Num. : GBJ2700Z

Model : RENAULT KANGOO 1.5 DCI AT EU6 90BHP

Chassis/Eng# : VF1FWT8H361486566/K9KF647D092486

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	750.00	✓ 750.00
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	420.00	✓ 420.00
REAR BUMPER REINFORCEMENT FRAME GARNISH <i>crushed</i>	1	340.00	✓ 340.00
REAR BUMPER REVERSE SENSOR <i>1 piece. Danged</i>	2	220.00	220 x 440.00
REAR BUMPER REVERSE SENSOR HOLDER COVER - SET <i>new</i>	1	150.00	150 150.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>Snapped</i>	1	420.00	✓ 420.00
REAR BUMPER RH REFLECTOR <i>crushed</i>	1	160.00	✓ 160.00
REAR BUMPER SIDE RETAINER BRACKET L/R <i>RH Danged</i>	2	150.00	150 300.00
REAR END PANEL <i>Dented</i>	1	700.00	✓ 700.00
REAR END PANEL INNER TOP GARNISH <i>crushed</i>	1	280.00	✓ 280.00
REAR RH FENDER <i>Buckled</i>	1	2200.00	1800 2,200.00
REAR RH FENDER AIR VENT <i>Dehnd.</i>	1	140.00	✓ 140.00
REAR RH FENDER INNER SHIELD <i>torn</i>	1	220.00	✓ 220.00
REAR RH FENDER INNER TRIM BOARD <i>crushed</i>	1	350.00	✓ 350.00
REAR RH FENDER MUDFLAP <i>Dehnd</i>	1	260.00	✓ 260.00
REAR RH GATE DOOR <i>Dented</i>	1	1790.00	✓ 1,790.00
REAR RH GATE DOOR 'KANGOO' EMBLEM <i>given</i>	1	130.00	✓ 130.00
REAR RH GATE DOOR 'MAXI' EMBLEM	1	60.00	✓ 60.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

BARRELS N LITRES PTE LTD
 13 JOO KOON CRESCENT
 SINGAPORE 629021

Contact : 93832360, 90281850

TAX INVOICE

Repair Code : CLM15326

Date in : 31/10/2022

Vehicle Num. : GBJ2700Z

Model : RENAULT KANGOO 1.5 DCI AT EU6 90BHP

Chassis/Eng# : VF1FWT8H361486566/K9KF647D092486

REAR RH GATE DOOR 'RENAULT' EMBLEM	<i>Nu</i>	1	149.00	✓	149.00
REAR RH GATE DOOR CHECKER	<i>He nu</i>	1	140.00	x	140.00
REAR RH GATE DOOR INNER TRIM BOARD	<i>He nu</i>	1	195.00	x	195.00
REAR RH GATE DOOR LOWER HINGE	<i>He nu</i>	1	155.00	x	155.00
REAR RH GATE DOOR LOWER LOCK	<i>He nu</i>	1	220.00	x	220.00
REAR RH GATE DOOR SPRING LINK	<i>Byd</i>	1	110.00	✓	110.00
REAR RH GATE DOOR VERTICAL RUBBER SEAL	<i>He nu</i>	1	235.00	x	235.00
REAR RH TAILLAMP	<i>could</i>	1	290.00	✓	290.00
REAR RH TAILLAMP INNER PANEL	<i>Regi</i>	1	330.00	+	330.00
REAR RH TAILLAMP LOWER GARNISH	<i>Del d.</i>	1	260.00	✓	260.00
REAR RH TAILLAMP OUTER PANEL	<i>Dented</i>	1	400.00	✓	400.00
REAR TAILGATE WEATHER STRIP SEAL	<i>Set</i>	1	330.00	✓	330.00

Subtotal before discount

11,924.00

Percentage discount 0%

0.00

Sub-total 1

11,924.00

REAR BUMPER CLIPS - SET	<i>Nu</i>	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Nu</i>	1	30.00	10	30.00
REAR RH FENDER INNER SHIELD CLIPS - SET	<i>Nu</i>	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature. ***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BARRELS N LITRES PTE LTD
13 JOO KOON CRESCENT
SINGAPORE 629021

Contact : 93832360, 90281850

TAX INVOICE

Repair Code : CLM15326

Date in : 31/10/2022

Vehicle Num. : GBJ2700Z

Model : RENAULT KANGOO 1.5 DCI AT EU6 90BHP

Chassis/Eng# : VF1FWT8H361486566/K9KF647D092486

REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	30.00	<i>X</i>	30.00
REAR RH FENDER INNER TRIM MAT <i>new</i>	1	480.00	<i>X</i>	480.00
REAR RH GATE DOOR 'SPAX' STICKER <i>3 new</i>	1	25.00	<i>15</i>	25.00
REAR RH GATE DOOR '70KM/H' STICKER	1	25.00	<i>15</i>	25.00
REAR RH GATE DOOR GLASS SEAL <i>new</i>	1	80.00	<i>30</i>	80.00
REAR RH GATE DOOR GLASS SEALANT <i>new</i>	1	60.00	<i>30</i>	60.00
REAR RH GATE DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	40.00	<i>X</i>	40.00
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	30.00	<i>10</i>	30.00
REAR RH TAILLAMP LOWER GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>10</i>	30.00
Subtotal before discount				930.00
Percentage discount 0%				0.00
Sub-total 2				930.00
Parts-total				12,854.00

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

X 250.00
50 ~~80~~ 100.00
80 120.00
60 150.00
80 1,500.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

BARRELS N LITRES PTE LTD
13 JOO KOON CRESCENT
SINGAPORE 629021

Contact : 93832360, 90281850

TAX INVOICE

Repair Code : CLM15326

Date in : 31/10/2022

Vehicle Num. : GBJ2700Z

Model : RENAULT KANGOO 1.5 DCI AT EU6 90BHP

Chassis/Eng# : VF1FWT8H361486566/K9KF647D092486

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

4,620.00

17,474.00

*** This is a computer-generated document which requires no signature.***

page 4

total: 11546.10

1/5: 89.2K.

09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: