

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Venessa Chan

Date: 04 Nov 2022

Preliminary Advice

Vehicle No	: FBB7707P	Accident Date	: 22/10/2022
Make	: YAMAHA YZF-R6S	Policy No.	: PNMC2022-00004679
Assignment Date	: 02/11/2022	Excess	: S\$0.00
Date of Inspection	: 03/11/2022	Est. Duration of Repair	: 0
Inspection At	: BAN HOCK HIN CO. PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410		

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	11,888.95
Revised Amount	:S\$	8,526.25
Check Items (Estimated)	:S\$	2,544.60
Total	:S\$	11,070.85
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	2,758.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 7,242.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.