

Ban Hock Hin Co. Pte Ltd (Co.Reg.No:197000288K)

No. 6 Defu Lane 4
Singapore 539410

Tel: 62816520 Fax: 62842969 Email: raymond@bhh.com.sg; audrey@bhh.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	PNMC2022-00004679	Date of Loss:	22/10/2022
Vehicle Reg. No.:	FBB7707P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ABDUL HAFFIZ BIN ABDUL ALEEM	Contact No:	+6591894548
Make/Model:	YAMAHA YZF-R6S, 599CC	Vehicle Reg. Date:	18/07/2007
Vehicle Colour:	WHITE/RED	Chassis No:	JYARJ111000023628
Engine No:	J511E028285		
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	BAN HOCK HIN CO. PTE LTD (HQ)		

*not Authorized
here
marcus
tel: 025635861
\$4145? TOTAL LOSS?*

COST OF CLAIMS

	Amount
Parts	11,168.95
Miscellaneous Items	0.00
Labour	720.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	11,888.95
+ GST 7.00% (\$\$)	832.23
Nett Amount (\$\$)	12,721.18

This claim is handled by: **TAN CHOK LOK**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Nov 2022)

Parts: N/A YAMAHA YZF-R6S 599cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ban Hock Hin Co. Pte Ltd/FBB7707P/02/11/2022 14:28

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bttery <i>17 X</i>	0.00	0.00	*140.00 F
2	2		*Bearing Steering Cone Lower <i>3N ✓</i>	0.00	0.00	*96.00 F
3	1		*Bolt Damper <i>3N ✓</i>	0.00	0.00	*2.00 F
4	1		*Bracket 5 <i>3N ✓</i>	0.00	0.00	*15.00 F
5	1		*Bracket 7 <i>3N ✓</i>	0.00	0.00	*30.00 F
6	1		*Bracket Side Stand <i>3N ✓</i>	0.00	0.00	*50.00 F
7	1		*Cable Clutch <i>3N ✓</i>	0.00	0.00	*50.00 F
8	1		*Cable Throttle <i>3N ✓</i>	0.00	0.00	*29.00 F
9	1		*Caliper Brake Front Assy LH <i>3N ✓</i>	0.00	0.00	*625.00 F
10	1		*Cap Coolant <i>3N ✓</i>	0.00	0.00	*7.00 F
11	1		*Cap Radiator <i>3N ✓</i>	0.00	0.00	*22.80 F
12	1		*Chain <i>3N ✓</i>	0.00	0.00	*160.00 F
13	1		*Clamp 1 <i>3N ✓</i>	0.00	0.00	*8.00 F
14	1		*Clip <i>1N ✓</i>	0.00	0.00	*3.00 F
15	2		*Clip Fork Front <i>3N ✓</i>	0.00	0.00	*4.00 F
16	4		*Clip Hose <i>3N ✓</i>	0.00	0.00	*8.00 F
17	1		*Coil Ignition <i>3N ✓</i>	0.00	0.00	*100.00 F
18	1		*Coolant <i>1N ✓</i>	0.00	0.00	*25.00 F
19	1		*Cord Starter Motor <i>3N ✓</i>	0.00	0.00	*69.00 F
20	1		*Cover 1 <i>3N ✓</i>	0.00	0.00	*11.00 F
21	1		*Cover Crankcase Magnet <i>3N ✓</i>	0.00	0.00	*79.00 F
22	1		*Cover Radiator <i>3N ✓</i>	0.00	0.00	*6.00 F
23	1		*Cover Sprocket Front <i>3N ✓</i>	0.00	0.00	*16.00 F
24	1		*Cover Strainer Assy <i>3N ✓</i>	0.00	0.00	*142.00 F
25	1		*Coverset Assy For 4E 4T X <i>3N ✓</i>	0.00	0.00	*1,060.60 F
26	1		*Damper 2 <i>3N ✓</i>	0.00	0.00	*2.00 F
27	1		*Damper Air Shroud <i>3N ✓</i>	0.00	0.00	*2.00 F
28	1		*Damper Air Shroud 3 <i>3N ✓</i>	0.00	0.00	*2.00 F
29	2		*Damper Locating <i>3N ✓</i>	0.00	0.00	*8.00 F
30	1		*Dust Cover Shift Shaft <i>3N ✓</i>	0.00	0.00	*3.00 F
31	1		*Fan Radiator <i>3N ✓</i>	0.00	0.00	*262.00 F
32	1		*Filter Oil <i>3N ✓</i>	0.00	0.00	*28.00 F
33	1		*Fork Tube Inner LH <i>17 X</i>	0.00	0.00	*340.90 F
34	1		*Fuel Pipe 1 <i>3N ✓</i>	0.00	0.00	*37.00 F
35	1		*Gasket Crankcase Cover 1 <i>3N ✓</i>	0.00	0.00	*15.00 F
36	4		*Gasket Exhaust Pipe <i>1N ✓</i>	0.00	0.00	*32.00 F
37	1		*Gasket Oil Pump Cover 1 <i>1N ✓</i>	0.00	0.00	*15.00 F
38	1		*Gasket Strainer Cover <i>1N ✓</i>	0.00	0.00	*13.00 F
39	1		*Guide Side Stand <i>3N ✓</i>	0.00	0.00	*24.00 F
40	1		*Horn <i>3N ✓</i>	0.00	0.00	*37.00 F
41	1		*Hose <i>3N ✓</i>	0.00	0.00	*11.00 F

Ban Hock Hin Co. Pte Ltd/FBB7707P/02/11/2022 14:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	1		*Hose 3N	0.00	0.00	*4.00 F
43	1		*Hose 3N	0.00	0.00	*37.00 F
44	1		*Hose 1 3N	0.00	0.00	*14.00 F
45	1		*Hose 2 3N	0.00	0.00	*11.00 F
46	1		*Hose 3 3N	0.00	0.00	*4.00 F
47	1		*Hose 4 3N	0.00	0.00	*21.00 F
48	1		*Hose 5 3N	0.00	0.00	*5.00 F
49	1		*Hose 7 3N	0.00	0.00	*12.00 F
50	1		*Hose 8 3N	0.00	0.00	*19.00 F
51	2		*Hose Bend 1 3N	0.00	0.00	*16.00 F
52	1		*Hose Brake (HEL) 3N	0.00	0.00	*190.90 F
53	2		*Hose Clamp Assy (Bottom Hose) 3N	0.00	0.00	*10.00 F
54	2		*Hose Elbow Radiator 3N	0.00	0.00	*7.40 F
55	1		*Joint Hose 2 3N	0.00	0.00	*30.00 F
56	1		*Joint Shift Shaft 3N	0.00	0.00	*20.00 F
57	2		*Joint, Carbruretor 1	0.00	0.00	? *64.00 F
58	2		*Joint, Carbruretor 2	0.00	0.00	? *64.00 F
59	1		*Mid Seal Oil (12x22x5) Pedal Gear 3N	0.00	0.00	*5.00 F
60	1		*Motor Starter Assy 3N	0.00	0.00	*319.00 F
61	1		*Oil Brake Dot 4	0.00	0.00	*14.60 F
62	4		*Oil Engine	0.00	0.00	*51.60 F
63	1		*Oil Fork 11 50%	0.00	0.00	*7.50 F
64	2		*O-Ring 11	0.00	0.00	*3.40 F
65	1		*Pedal Gear Assy 3N	0.00	0.00	*91.00 F
66	1		*Pipe 1 3N	0.00	0.00	*11.00 F
67	1		*Pipe Exhaust Assy 3N	0.00	0.00	*2,046.00 F
68	1		*Pipe Hose Radiator 3N	0.00	0.00	*28.00 F
69	1		*Plate Radiator 3N	0.00	0.00	*8.00 F
70	1		*Protector Heat 3N	0.00	0.00	*57.00 F
71	1		*Radiator Assy 3N	0.00	0.00	*387.00 F
72	1		*Rectifier & Regulator Assy 3N	0.00	0.00	*104.00 F
73	1		*Relay Replacement 3N	0.00	0.00	*28.00 F
74	1		*Rod Shift 1 3N	0.00	0.00	*34.00 F
75	2		*Seal Dust Fork 11 X	0.00	0.00	*22.00 F
76	2		*Seal Oil Fork 112	0.00	0.00	*40.00 F
77	1		*Shift Arm 3N	0.00	0.00	*57.00 F
78	1		*Spring Tension 3N	0.00	0.00	*6.00 F
79	1		*Sprocket Front 3N	0.00	0.00	*74.00 F
80	1		*Sprocket Rear Std 3N	0.00	0.00	*85.00 F
81	1		*Stand Side 3N	0.00	0.00	*177.00 F
82	1		*Stator Assy ?	0.00	0.00	*308.00 F
83	1		*Switch Side Stand 3N	0.00	0.00	*66.00 F
84	1		*Tank Coolant Recovery 3N	0.00	0.00	*24.00 F
85	1		*Thermosensor Assy 3N	0.00	0.00	*56.60 F
86	1		*Throttle Body Assy ?	0.00	0.00	*1,989.00 F
87	1		*Valve Solenoid ?	0.00	0.00	*105.00 F
88	1		*Wire Harness Assy 3N	0.00	0.00	*819.00 F
89	5		*Petrol m X	0.00	0.00	*18.50 F
90	11		*Tube 3N	0.00	0.00	*7.15 F

F=Franchise part.

Total Parts (\$\$)

11,168.95

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Labour	New	720.00
			<i>500</i>
		Gross Labour Cost (\$\$)	720.00

Ban Hock Hin Co. Pte Ltd/FBB7707P/02/11/2022 14:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >