

SERVICE ESTIMATE

0 - F00003 SL: MS FIRST CAPITAL INSURANCE LTD MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01, CITY HOUSE SINGAPORE Singapore 068877	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 1 Inv.date. : 11/03/2023 WIP No. . : 47471 Veh.In/Out: 15/02/2023 08/03/2023 *Tel.No. . : Reg.No. . : SLL5486T Reg.date .: 28/02/2017 Mileage .: 53,549 Chassis No: YV1MV28H0H2412508
---	--

Closed by : Michelle Ong Siew Be Svc Consultant : ACC Remarks : Mr Yu Qi	
---	--

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE RHR DOOR, RHR FENDER, REAR BUMPER, BRACKETS, CLIPS, ETC.	0	3825.00	0		3,825.00	S
800	TO BLEND AND SPRAY PAINT ON RHR DOOR, RHR FENDER, RHS FENDER INNER PANEL, RHS ROOF TOP SIDE PANEL, REAR BUMPER, ETC.	0	3000.00	0		3,000.00	S
802	TO REPLACE RHR QTR GLASS	0	850.00	0		850.00	S
89994	TO INSTALL RHR QTR GLASS	0	280.00	0		280.00	S
	SOLAR FILM						
802	TO REMOVE AND INSTALL INTERIOR PARTS	0	1700.00	0		1,700.00	S
802	TO REMOVE AND INSTALL REAR BOO	0	850.00	0		850.00	S
	COMPARTMENT PARTS						
802	TO REMOVE AND INSTALL PETROL TANK	0	850.00	0		850.00	S
0031	TO REPLACE RHR RIM	0	50.00	0		50.00	S

SERVICE ESTIMATE

0 - F00003 SL: MS FIRST CAPITAL INSURANCE LTD
 MS FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X
 36 ROBINSON ROAD Inv.No. . : B&P 0 Page 2
 #16-01, CITY HOUSE Inv.date. : 11/03/2023
 SINGAPORE WIP No. . : 47471
 Singapore 068877 Veh.In/Out: 15/02/2023 08/03/2023
 *Tel.No. . :
 Reg.No. . : SLL5486T
 Closed by : Michelle Ong Siew Be Reg.date . : 28/02/2017
 Svc Consultant : ACC Mileage .. : 53,549
 Remarks : Mr Yu Qi Chassis No: YV1MV28H0H2412508

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
10	WHEEL ALIGNMENT	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00	S
①	ALLOY RIM 16 "Markeb	1.0 EA	749.10	10		674.19	S
②	BUMPER COVER REAR V4	1.0 EA	1865.70	10		1,679.13	S
③	FENDER REAR RH V40/C	1.0 EA	1723.40	10		1,551.06	S
④	NOISE DEADENING PAD	3.0 EA	606.90	10		1,638.63	S
⑤	SEAM SEALANT	1.0 EA	49.00	10		44.10	S
⑥	QTR GLASS BLACK RH V	1.0 EA	560.60	10		504.54	S
⑦	*D* REPAIR SEALANT G	1.0 EA	761.80	10		685.62	S
⑧	2-PART FLEXIBLE FOAM	1.0 EA	210.00	10		189.00	S
⑨	PLASTIC ADHESIVE WUR	1.0 EA	70.00	10		63.00	S
⑩	*D* PRIMER GLASS & P	1.0 EA	45.50	10		40.95	S
⑪	*D* GLASS CLEANER H	1.0 EA	86.60	10		77.94	S
⑫	*D* WINDSCREEN SEALA	2.0 EA	172.70	10		310.86	S
⑬	BUMPER INSTALLING MT	1.0 EA	101.40	10		91.26	S

SERVICE ESTIMATE

O - F00003 MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01, CITY HOUSE SINGAPORE Singapore 068877	SL: MS FIRST CAPITAL INSURANCE LTD GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 3 Inv.date. : 11/03/2023 WIP No. . : 47471 Veh.In/Out: 15/02/2023 08/03/2023 *Tel.No. . : Reg.No. . : SLL5486T Reg.date . : 28/02/2017 Mileage .. : 53,549 Chassis No: YV1MV28H0H2412508
Closed by : Michelle Ong Siew Be Svc Consultant : ACC Remarks : Mr Yu Qi	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
16	BUMPER CLIP XC90 16-	10.0 EA	8.80	10		79.20	S
17	BLIND RIVET 4.0*21 P	10.0 EA	5.00	10		45.00	S
18	BUMPER CLIP 8x8,5	10.0 EA	8.20	10		73.80	S
19	BUMPER CLIP GREEN S6	10.0 EA	6.00	10		54.00	S
20	EXPANDING NUT XC40 1	10.0 EA	6.70	10		60.30	S

		Gross Total.	20,135.58
Labour Total	12,273.00	Net.....	20,135.58
Parts Total	7,862.58	GST @ 8.0%	1,610.85
Package Total	0.00	Total.....	21,746.43
		Paid.....	0.00
		Please Pay..	21,746.43

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate