



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 7951S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	TORN	390.00	390.00
1	FRONT BUMPER REINFORCEMENT (WCP)	TO REPAIR SEE LABOUR	195.00	-
1	FRONT BUMPER SPONGE (WCP)	CRACKED	70.00	70.00
1	FRONT BUMPER LH SIDE RETAINER (WCP)	CRACKED	36.00	36.00
1	FRONT BUMPER LH FOG LAMP (WCP)	MTG CRACKED	105.00	105.00
1	FRONT BUMPER LH FOG LAMP BRACKET (WCP)	CRACKED	70.00	70.00
1	FRONT BUMPER LH FOG LAMP CHROME COVER (WCP)	DENTED	65.00	65.00
1	FRONT BUMPER INNER TOP RUBBER (WCP)	NECESSARY	45.00	45.00
1	FRONT BUMPER LH WIPER NOZZLE ASSY (WCP)	BROKEN	220.00	220.00
1	FRONT BUMPER LH WIPER NOZZLE COVER (WCP)	MISSING	16.00	16.00
1	FRONT BUMPER LH WIPER NOZZLE HOSE TUBE (WCP)	TORN	75.00	75.00
8	FRONT BUMPER CLIP @\$1.50 (WCP)	NOT NECESSARY	12.00	-
1	FRONT GRILLE HOUSING (WCP)	CRACKED	390.00	390.00
1	FRONT GRILLE OUTER CHROME (WCP)	DENTED	140.00	140.00
1	FRONT GRILLE LOGO (WCP)	SERVICEABLE	195.00	-
1	FRONT LH FENDER (WCP)	BUCKLED	360.00	360.00
1	FRONT LH FENDER INNER SHIELD (WCP)	DISTORTED	125.00	125.00
1	FRONT LH FENDER EXTENSION BRACKET (WCP)	DISTORTED	62.00	62.00
1	FRONT LH FENDER SIDE BRACKET (WCP)	BENT	29.00	29.00
1	FRONT LH FENDER INNER TOP PROTECTOR (WCP)	BUCKLED	95.00	95.00
8	FRONT LH FENDER INNER TOP PROTECTOR CLIPS @ \$1.50 (WCP)	NOT NECESSARY	12.00	-
6	FRONT LH FENDER INNER SHIELD CLIP @\$1.50 (WCP)	NECESSARY	9.00	9.00
1	BONNET (WCP)	BENT	720.00	720.00
1	BONNET INNER TOP RUBBER (WCP)	SERVICEABLE	28.00	-
1	BONNET LH HINGE (WCP)	TO REPAIR SEE LABOUR	38.00	-
1	FRONT BUMPER LH PARKING SENSOR (WCP)	CRACKED	155.00	155.00
1	FRONT BUMPER PDC SENSOR WIRE HARNESS (WCP)	TORN	210.00	210.00
1	HEADLAMP LH (WCP)	BROKEN	800.00	800.00
1	HEADLAMP LH HID BULB (WCP)	BROKEN	180.00	180.00

Report Ref No. CS/SMO22010958/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP LH CONTROL UNIT (WCP)	SHORTED	330.00	330.00
1	HEADLAMP LH COVER NO.1 (WCP)	SERVICEABLE	50.00	-
1	HEADLAMP LH BULB CORD (WCP)	SERVICEABLE	60.00	-
1	FRT SUPPORT PANEL (WCP)	BUCKLED	530.00	530.00
1	FRONT SUPPORT PANEL INNER TOP GARNISH (WCP)	SERVICEABLE	140.00	-
8	FRONT SUPPORT PANEL INNER TOP GARNISH CLIP @ \$1.50 (WCP)	NECESSARY	12.00	12.00
1	RADIATOR LH SIDE GARNISH (WCP)	DISTORTED	60.00	60.00
1	BATTERY INSULATOR (WCP)	SERVICEABLE	80.00	-
	COST PLUS 15%		610.90	529.90
			6,719.90	5,828.90
	<u>SPECIAL NETT ITEMS</u>			
1	CUNIT COOLANT (SN)	NECESSARY	35.00	35.00
1	FRONT NUMBER PLATE (SN)	DENTED	35.00	35.00
1	FRONT LH TYRE PRESSURE MONITOR SENSOR (SN) (ADDITIONAL)	DENTED / SHORTED	280.00	280.00
			350.00	350.00
	<u>LABOUR</u>			
	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS .		100.00	100.00
	REMOVE & REFIX FRT BUMPER & ATTACHMENTS GRILLE BONNET & ATTACHMENTS ,HEADLAMPS,FRT LH FENDER,TO CUT ,WELD & RENEW FRT SUPPORT PANEL ,KNOCKING & REPAIR FRT LH CHASSIS FRAME & FRT LH FENDER INNER PANEL REALIGN FRT LH DOOR THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND BONNET LH HINGE.		900.00	600.00
	PUTTY & RESPRAY FRT BUMPER ,REINFORCEMENT ,PARKING SENSORS ,BONNET & ATTACHMENTS ,BONNET ,FRT LH FENDER & INNER PANEL ,FRT SUPPORT PANEL ,FRT LH CHASSIS FRAME ,FRT LH DOOR & ALL AFFECTED AREAS .		800.00	800.00
	REMOVE & REFIX FRT PARKING SENSORS WIRE HARNESS & RESET.		80.00	60.00

Report Ref No. CS/SMO22010958/Kny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX FRT LH TYRE PRESSURE MONITOR SENSOR CLEAR FAULT CODE & RESET THE SAME. (ADDITIONAL)		80.00	80.00
			1,960.00	1,640.00
GRAND TOTAL			9,029.90	7,818.90

RECOMMENDED COST OF REPAIRS			7,818.90
LESS EXCESS			-700.00
NETT LIABILITY			7,118.90

Report Ref No. CS/SMO22010958/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.