

Not Authorised
Resurvey B4 paint
Ex TBA

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

6 days

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department
WS Ref: OD/SOMPO/AMK
Claim Type: Own Damage
Accident Date: 29/10/2022

Claim No: ES2291125
Estimate No: ES2291125/AMK
Date: 02 Nov 2022
Policy No: D22MTPV01008996
Veh Reg No: SNE7951S
Make/Model: LEXUS ES250
Chassis No: JTHBJ1GG002077985
Engine No: 2ARF002668
Reg. Date: 28/04/2015

Estimate Repair Cost to Vehicle No : SNE7951S

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Cost Plus				
1 FRONT BUMPER	390.00	1 PC	390.00	✓
2 FRONT BUMPER REINFORCEMENT	195.00	1 PC	195.00	?
3 FRONT BUMPER SPONGE	70.00	1 PC	70.00	?
4 FRONT BUMPER LH SIDE RETAINER	36.00	1 PC	36.00	✓
5 FRONT BUMPER LH FOG LAMP	105.00	1 PC	105.00	✓
6 FRONT BUMPER LH FOG LAMP BRACKET	70.00	1 PC	70.00	✓
7 FRONT BUMPER LH FOG LAMP CHROME COVER	65.00	1 PC	65.00	✓
8 FRONT BUMPER INNER TOP RUBBER	45.00	1 PC	45.00	✓
9 FRONT BUMPER LH WIPER NOZZLE ASSY	220.00	1 PC	220.00	✓
10 FRONT BUMPER LH WIPER NOZZLE COVER	16.00	1 PC	16.00	✓
11 FRONT BUMPER LH WIPER NOZZLE HOSE TUBE	75.00	1 PC	75.00	✓
12 FRONT BUMPER CLIP	1.50	8 PC	12.00	✓
13 FRONT GRILLE HOUSING	390.00	1 PC	390.00	?
14 FRONT GRILLE OUTER CHROME	140.00	1 PC	140.00	✓
15 FRONT GRILLE LOGO	195.00	1 PC	195.00	?
16 FRONT LH FENDER	360.00	1 PC	360.00	✓
17 FRONT LH FENDER INNER SHIELD	125.00	1 PC	125.00	?
18 FRONT LH FENDER EXTENSION BRACKET	62.00	1 PC	62.00	✓
19 FRONT LH FENDER SIDE BRACKET	29.00	1 PC	29.00	✓
20 FRONT LH FENDER INNER TOP PROTECTOR	95.00	1 PC	95.00	✓
21 FRONT LH FENDER INNER TOP PROTECTOR CLIPS	1.50	8 PC	12.00	✓
22 FRONT LH FENDER INNER SHIELD CLIP	1.50	6 PC	9.00	✓
23 BONNET	720.00	1 PC	720.00	✓
24 BONNET INNER TOP RUBBER	28.00	1 PC	28.00	X
25 BONNET LH HINGE	38.00	1 PC	38.00	X
26 FRONT BUMPER LH PARKING SENSOR	155.00	1 PC	155.00	✓
27 FRONT BUMPER PDC SENSOR WIRE HARNESS	210.00	1 PC	210.00	✓
28 HEADLAMP LH	800.00	1 PC	800.00	✓
29 HEADLAMP LH HID BULB	180.00	1 PC	180.00	✓
30 HEADLAMP LH CONTROL UNIT	330.00	1 PC	330.00	?
31 HEADLAMP LH COVER NO.1	50.00	1 PC	50.00	?
32 HEADLAMP LH BULB CORD	60.00	1 PC	60.00	?
33 FRT SUPPORT PANEL	530.00	1 PC	530.00	✓
34 FRONT SUPPORT PANEL INNER TOP GARNISH	140.00	1 PC	140.00	X
35 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	1.50	8 PC	12.00	✓
36 RADIATOR LH SIDE GARNISH	60.00	1 PC	60.00	?
37 BATTERY INSULATOR	80.00	1 PC	80.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555 FAX: 62213302
 ATTN: Motor Claim Department
 WS Ref: OD/SOMPO/AMK
 Claim Type: Own Damage
 Accident Date: 29/10/2022

Claim No: ES2291125
 Estimate No: ES2291125/AMK
 Date: 02 Nov 2022
 Policy No: D22MTPV01008996
 Veh Reg No: SNE7951S
 Make/Model: LEXUS ES250
 Chassis No: JTHBJ1GG002077985
 Engine No: 2ARF002668
 Reg. Date: 28/04/2015

Estimate Repair Cost to Vehicle No : SNE7951S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
			6,109.00	
	Add 10%		610.90	6,719.90

Special Net

38 COOLANT	35.00	1 UNIT <i>mu</i>	35.00	✓
39 FRONT NUMBER PLATE	35.00	1 PC <i>na</i>	35.00	✓
				70.00

Labour

40 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
41 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,HEADLAMPS,FRT LH FENDER;TO CUT,WELD & RENEW FRT SUPPORT PANEL;KNOCKING & REPAIR FRT LH CHASSIS FRAME & FRT LH FENDER INNER PANEL & REALIGN FRT LH DOOR THE SAME	900.00	1 LA	900.00	600
42 PUTTY & RESPRAY FRT BUMPER,REINFORCEMENT,PARKING SENSORS,BONNET & ATTACHMENTS,BONNET,FRT LH FENDER & INNER PANEL,FRT SUPPORT PANEL,FRT LH CHASSIS FRAME,FRT LH DOOR & ALL AFFECTED AREAS	800.00	1 LA	800.00	✓
43 REMOVE & REFIX FRT PARKING SENSORS WIRE HARNESS & RESET	80.00	1 LA	80.00	60
				1,880.00

Total S\$ 8,669.90

Add GST @ 7% 606.89

Total Amount payable S\$ 9,276.79

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE