

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-61

SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Tel : 6389 - 6111  
Fax : 6224 - 7478 / 7175

Quotation  
DATE : 11.11.2022  
VEH NO : SMD9043S  
MODEL : Mazda CX5  
D O A : 28.10.2022  
YR REF : SNM22D207763/C02

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMD9043S (MAZDA CX5)

| Item                         | Description                                      | Qty | Amt                      |
|------------------------------|--------------------------------------------------|-----|--------------------------|
| <b>NO LIST ITEMS - FRONT</b> |                                                  |     |                          |
| 1                            | Front Number Plate Garnish <i>He m</i>           | 1   | 101.60 <i>X.</i>         |
| 2                            | Front Bumper <i>Deband</i>                       | 1   | 1,023.10 <i>✓</i>        |
| 3                            | Front Bumper Side Holder - LH & RH <i>band</i>   | 2   | 70.80 <i>✓</i>           |
| 4                            | Front Bumper Reinforcement <i>new</i>            | 1   | 594.80 <i>X.</i>         |
| 5                            | Front Bumper Sponge - LH & RH <i>new</i>         | 2   | 95.60 <i>X.</i>          |
| 6                            | Front Bumper Tow Cover <i>new</i>                | 1   | 38.40 <i>X.</i>          |
| 7                            | Front Bumper Sensor - LH & RH <i>1 piece dnd</i> | 2   | 723.60 <i>361.80</i>     |
| 8                            | Front Bumper Side Garnish - LH & RH <i>new</i>   | 2   | 98.20 <i>X.</i>          |
| 9                            | Front Grille <i>crushed</i>                      | 1   | 1,020.40 <i>10066.70</i> |
| 10                           | Front Grille Logo <i>new</i>                     | 1   | 59.40 <i>✓</i>           |
| 11                           | Front Grille Bracket - LH & RH <i>crushed</i>    | 2   | 116.20 <i>8053.36</i>    |
| 12                           | Front Grille Chrome Moulding - LH & RH <i>at</i> | 2   | 290.40 <i>✓</i>          |
| 13                           | Headlamp - LH & RH <i>crushed</i>                | 2   | 7,124.60 <i>✓</i>        |

**LIST ITEMS - REAR**

|    |                                               |   |                        |
|----|-----------------------------------------------|---|------------------------|
| 14 | Rear Bumper <i>Deband</i>                     | 1 | 1,278.50 <i>✓</i>      |
| 15 | Rear Bumper Side Holder - LH & RH <i>band</i> | 2 | 96.00 <i>✓</i>         |
| 16 | Rear Bumper Reinforcement <i>Deband</i>       | 1 | 686.70 <i>✓</i>        |
| 17 | Rear Bumper Reflector - LH & RH <i>new</i>    | 2 | 216.40 <i>X.</i>       |
| 18 | Reverse Sensor <i>2 pieces dnd</i>            | 4 | 1,124.60 <i>560.80</i> |
| 19 | Rear End Panel <i>new</i>                     | 1 | 622.80 <i>X.</i>       |
| 20 | Rear End Panel Top Garnish <i>new</i>         | 1 | 178.20 <i>X.</i>       |
| 21 | Tailgate <i>Deband</i>                        | 1 | 1,558.50 <i>✓</i>      |
| 22 | Tailgate Lock <i>band</i>                     | 1 | 385.90 <i>✓</i>        |
| 23 | Tailgate Weatherstripe <i>new</i>             | 1 | 185.90 <i>X.</i>       |
| 24 | Tailgate Glass Moulding <i>new</i>            | 1 | 189.60 <i>✓</i>        |
| 25 | Mazda Logo <i>new</i>                         | 1 | 78.90 <i>✓</i>         |

RE: **ESTIMATE FOR ACCIDENT REPAIR SMD9043S (MAZDA CX5)**

26 CX5 Wording *new*

4914.80 1

3931.84

Less 20%

79.90 ✓

|    |            |
|----|------------|
| \$ | 18,036.00  |
|    | (3,607.20) |
| \$ | 14,428.80  |

**S/NETT ITEMS - FRONT**

- |   |                           |              |       |       |          |
|---|---------------------------|--------------|-------|-------|----------|
| 1 | Front Number Plate        | <i>3 new</i> | 1     | 30.00 | <i>x</i> |
| 2 | Front Number Plate Holder |              | 1     | 30.00 | <i>x</i> |
| 3 | Front Bumper Clips        | <i>new</i>   | 1 set | 30.00 | <i>✓</i> |

**S/NETT ITEMS - REAR**

- |   |                                  |            |       |       |          |
|---|----------------------------------|------------|-------|-------|----------|
| 4 | Rear Bumper Clips                | <i>new</i> | 1 set | 30.00 | <i>✓</i> |
| 5 | Rear End Panel Top Garnish Clips | <i>new</i> | 1 set | 20.00 | <i>x</i> |
| 6 | Rear End Panel Sealant           | <i>new</i> | 1     | 60.00 | <i>x</i> |
| 7 | Tailgate Glass Sealant           | <i>new</i> | 1     | 60.00 | <i>✓</i> |

Total parts

\$ 14,688.80

**LABOUR CHARGE**

- |    |                                                          |  |
|----|----------------------------------------------------------|--|
| 1  | To knocking out front & rear portion & renew above parts |  |
| 2  | To putty & spray up paint works                          |  |
| 3  | To check wiring                                          |  |
| 4  | To remove front bumper sensor                            |  |
| 5  | To remove reverse sensor                                 |  |
| 6  | To remove rear camera                                    |  |
| 7  | To remove upholstery                                     |  |
| 8  | To spray tuff coat                                       |  |
| 9  | To transfer tailgate fittings                            |  |
| 10 | To remove tailgate glass                                 |  |

1970

|    |                     |            |
|----|---------------------|------------|
| \$ | <del>1,800.00</del> | <i>900</i> |
| \$ | <del>1,600.00</del> | <i>600</i> |
| \$ | <del>100.00</del>   | <i>60</i>  |
| \$ | <del>100.00</del>   | <i>50</i>  |
| \$ | <del>100.00</del>   | <i>50</i>  |
| \$ | <del>100.00</del>   | <i>50</i>  |
| \$ | <del>150.00</del>   | <i>30</i>  |
| \$ | <del>150.00</del>   | <i>30</i>  |
| \$ | <del>150.00</del>   | <i>80</i>  |
| \$ | <del>180.00</del>   | <i>120</i> |

Total Labour

\$ 4,430.00

Grand Total

**\$ 19,118.80**

total: 14075.20  
h/s: 11250  
07 Days.