

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22010963/An2y3	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623		Date:	02/11/2022	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SJV 3093C	Veh. Inspected		SMR 7291G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2203944/THE	Excess (\$)		0.00	
	Assign From	MELVIN YE	Assign Date		02/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	29/10/2022	Inspection Dat	е	02/11/2022	
	Survey held at	25 Kaki Bukit Road 4 #05-36/37 Synergy @ KB				
	Repairer	Divine Splash Spray Painting				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					