

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010970/AYA3Q2**Date:** 05/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100451096
Claimant Vehicle No :	SLM2422S	Insured Vehicle No :	SGD3068G
Date of Loss:	29/10/2022	Nature of Claim:	TP
		Claim No:	8909393521SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM2422S		
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Engine No:	27492030356851
Reg. Date:	28/08/2015 (Man. Year: 2015)	Chassis No:	WDD2050422R051870
Colour:	Grey	Odometer:	99809 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30 R19	Rear Tyre Size:	275/30 R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,332.50	5,202.90	9,129.60	63.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,160.00	800.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,292.50	6,362.90	9,929.60	60.95
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	16,292.50	5,000.00	11,292.50	69.31
+ GST 8.00/8.00% (S\$)	1,303.40	400.00	903.40	69.31
Nett Amount (S\$)	17,595.90	5,400.00	12,195.90	69.31
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		5,900.00		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment:	01/11/2022		
Date Inspected:	01/11/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Dented	2,760.00 FL	*2,760.00 FL
2	1		*REAR LH DOOR TOP HINGE	Damaged	190.00 FL	*190.00 FL
3	1		*REAR LH DOOR LOWER HINGE	Damaged	280.00 FL	*280.00 FL
4	1		*REAR LH DOOR OUTER CHROME	Not Necessary	175.00 FL	*- FL
5	1		*REAR LH DOOR OUTER MOULDING	Cut	90.00 FL	*90.00 FL
6	1		*REAR LH DOOR LOCK	Not Necessary	360.00 FL	*- FL
7	1		*REAR LH DOOR TRIMBOARD	Not Necessary	1,398.00 FL	*- FL
8	1		*FRT LH DOOR	Dented	2,125.00 FL	*2,125.00 FL
9	1		*FRT LH DOOR OUTER MOULDING	Not Necessary	138.00 FL	*- FL
10	1		*FRT LH DOOR CHROME	Not Necessary	162.00 FL	*- FL
11	1		*REAR LH DOOR RUBBER	Cut	336.00 FL	*336.00 FL
12	1		*REAR LH DOOR RUBBER	Not Necessary	336.00 FL	*- FL
13	1		*LH DOOR PILLAR	Not Necessary	7,575.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,925.00	5,781.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,592.50	578.10
Total Parts (\$\$)	14,332.50	5,202.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	TRANSFER 2 DOOR PARTS	New	160.00	160.00
Gross Labour Cost (S\$)			1,960.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >