

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0939/2022/EQ
DATE : 28-Oct-22
WIP : 47914

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/11/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR JUN NITTA
ADDRESS : 106 GRANGE ROAD, CLIVEDEN AT GRANGE
#06-05
SINGAPORE 249594
TELEPHONE : HP +65 82923896
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070060703-01
VEHICLE NO : **S 6825 CD**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 25/3/2020
ENGINE NO : CZD 891677
CHASSIS NO : WAUZZZF33L1078447
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Oct-22
PLACE OF ACCIDENT : SHANGRI-LA SINGAPORE, ORANGE GROVE RD

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE S 6825 CD

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	X
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	X
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	X
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	X
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 280	✓
TOTAL LABOUR CHARGES		:	\$ 4,660.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE S 6825 CD

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	X
8	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER AND REAR END PANELLING RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	1500 ✓
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, TWO DOOR COVERS, DOOR HANDLE, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 9,000.00	2350 ✓ SSO X 3 = 1650 Door handle : 100 Door Cover 200 Wheel Arc x 2 = 200 x 2 = 400
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 22,412.00	2350

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S 6825 CD

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Regis</i>	1	\$ 1,738.00	X	
2	REAR BUMPER SPOILER <i>Regis</i>	1	\$ 510.00	X	
3	REAR BUMPER ADAPTER - LH <i>Regis</i>	1	\$ 95.00	X	
4	REAR BUMPER GUIDE SECTION - LH <i>Regis</i>	1	\$ 71.00	X	
5	REAR SIDE PANEL - LH <i>Regis</i>	1	\$ 3,899.00	X	
6	REAR QUARTER WINDOW - LH <i>Regis</i>	1	\$ 683.00	+	
7	WINDOW PRIMER <i>Regis</i>	1	\$ 22.00	X	
8	REAR WHEEL SPOILER - LH <i>Regis</i>	1	\$ 44.00	X	
9	REAR SIDE MEMBER TRIM - LH <i>Regis</i>	1	\$ 189.00	+	
10	REAR WHEEL HOUSING LINER <i>Regis</i>	1	\$ 262.00	+	
11	REAR DOOR - LH <i>Derfied</i>	1	\$ 3,028.00	✓	7422.40
12	REAR OUTER DOOR SEAL - LH <i>Regis</i>	1	\$ 151.00	✓	120.40
13	REAR DOOR CATCH <i>Regis</i>	1	\$ 134.00	? X	
14	REAR SILL PANEL SEAL - LH <i>Regis</i>	1	\$ 151.00	+	
15	REAR INNER DOOR SEAL <i>Regis</i>	1	\$ 213.00	X	
16	REAR DOOR COVER - LH LOWER <i>Derfied</i>	1	\$ 368.00	✓	294.00
17	FRONT DOOR COVER - LH LOWER <i>Derfied</i>	1	\$ 390.00	✓	312.00
18	REAR DOOR HANDLE BASE <i>Regis</i>	1	\$ 182.00	X	
19	REAR DOOR BOWDEN CABLE <i>Regis</i>	1	\$ 58.00	X	
20	REAR DOOR HANDLE - LH <i>Regis</i>	1	\$ 223.00	X	
SUB TOTAL SPARE PARTS		:	\$ 12,411.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S 6825 CD

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR HOUSING - LH <i>Not m</i>	1	\$ 31.00	+	
22	REAR WINDOW REGULATOR - LH <i>Not m</i>	1	\$ 302.00	+	
23	REAR WINDOW REGULATOR MOTOR - LH <i>Not m</i>	1	\$ 300.00	+	
24	REAR DOOR CONTROL UNIT <i>Not m</i>	1	\$ 464.00	+	
25	REAR DOOR PANEL - LH <i>Not m</i>	1	\$ 2,659.00	+	
26	REAR WINDOW SLOT SEAL TRIM STRIP - LH OUTER <i>Not m</i>	1	\$ 305.00	+	
27	REAR WINDOW GUIDE TRIM STRIP - LH <i>Not m</i>	1	\$ 170.00	+	
28	REAR WHEEL COVER - LH / RH <i>Not m</i>	2	\$ 1,132.00	+	904.80
29	REAR CROSS PANEL <i>Not m</i>	1	\$ 445.00	+	
30	REAR ALUMINIUM RIM <i>Not m</i>	1	\$ 1,414.00	+	1131.20
31	REAR ALUMINIUM RIM RUBBER VALVE <i>Not m</i>	1	\$ 4.00	+	
32	ACRYLIC SEALANT	S/N	\$ 180.00	+	
33	CAVITY WAX	S/N	\$ 140.00	+	
34	STONE CHIP	S/N	\$ 180.00	+	
35	METAL FILLER POWDER	S/N	\$ 280.00	+	
36	1/4 GLASS SEALANT	S/N	\$ 100.00	+	
37	SUNDRIES <i>Not m</i>		\$ 500.00	+	10.16
TOTAL SPARE PARTS			\$ 21,017.00		
TOTAL LABOUR CHARGES			\$ 22,412.00		
GRAND TOTAL			\$ 43,429.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*
SURVEYED DATE : *02/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT