

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2210-594-TG
DATE : 2-Nov-2022
VEHICLE REG. NO. : **SMQ7451S**
VEHICLE MAKE : NISSAN SYLPHY 1.6 CVT
(29 11 2019)TO Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Fender RH	1		\$ -
2	Rear Windscreen Moulding	1		\$ -
3	Fuel Tank Cover	1		\$ -
4	Tail Lamp RH	1		\$ -
5	Tail Lamp Clips	1		\$ -
6	Tail Lamp RH Panel	1		\$ -
7	Bootlid Lamp RH	1		\$ -
8	Bootlid Emblem Sylphy	1		\$ -
9	Bootlid Emblem Nissan	1		\$ -
10	Rear Boot Inner Trim RH	1		\$ -
11	Rear Bumper	1		\$ -
12	Rear Bumper Retainer RH	1		\$ -
13	Front Rim RH	1		\$ -
14	Front Rim LH	1		\$ -
15	Rear Rim RH	1		\$ -
16	Support Panel	1		\$ -
17	Front Bumper Undercover	1		\$ -
18	Engine Undercover	1		\$ -
19	Front Fendershield RH	1		\$ -
20	Front Fendershield RH Flap	1		\$ -
21	Front Lower Arm RH	1		\$ -
22	Front Absorber RH	1		\$ -
23	Front Absorber Top Mount RH	1		\$ -
24	Front Absorber Bearing RH	1		\$ -
25	Front Wheelhub & Bearing RH	1		\$ -
26	Front Knuckle RH	1		\$ -
27	Front Tie Rod End RH	1		\$ -
28	Front Tie Rod Inner RH	1		\$ -
29	Front Stabiliser Linkage RH	1		\$ -
30	Front Lower Arm LH	1		\$ -
31	Front Absorber LH	1		\$ -
32	Front Absorber Top Mount LH	1		\$ -
33	Front Absorber Bearing LH	1		\$ -

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2210-594-TG
DATE : 2-Nov-2022
VEHICLE REG. NO. : **SMQ7451S**
VEHICLE MAKE : NISSAN SYLPHY 1.6 CVT
(29 11 2019)TO Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
34	Front Wheelhub & Bearing LH	1		\$ -
35	Front Knuckle LH	1		\$ -
36	Front Tie Rod End LH	1		\$ -
37	Front Tie Rod Inner LH	1		\$ -
38	Front Stabiliser Linkage LH	1		\$ -
39	Front Crossmember	1		\$ -
Total Spare Parts				\$ -
	<u>SPECIAL NETT</u>			
40	Rear Fendershield Clips	10	\$ 3.00	\$ 30.00
41	Front Bumper Clips	10	\$ 3.00	\$ 30.00
42	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
43	Front Fendershield RH Clips	10	\$ 3.00	\$ 30.00
44	Rear Tyre RH	1	\$ 200.00	\$ 200.00
45	Front Tyre RH	1	\$ 200.00	\$ 200.00
46	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
Total Special Nett				\$ 560.00
	<u>LABOUR</u>			
47	Remove, Refit, Replace and Repair Affected Area (Rocker Panel RH)	1	\$ 800.00	\$ 800.00
48	Replace Rear Fender RH, cut, weld & re-align	1	\$ 600.00	\$ 600.00
49	Spray painting (Rear Bumper, Rear Fender LH, Bootlid, Rocker Panel RH & LH, Front Bumper)	1	\$ 1,250.00	\$ 1,250.00
50	Remove and Replace Front Crossmember with Undercarriage LH & RH	1	\$ 400.00	\$ 400.00
51	Transfer Tyre and Balancing	3	\$ 40.00	\$ 120.00
52	Diagnose, Rectify and Reset Fault Codes	1	\$ 150.00	\$ 150.00
53	Remove and Replace Rear Windscreen	1	\$ 150.00	\$ 150.00
54	Wheel Alignment	1	\$ 70.00	\$ 70.00
55	Anti-Rust Coating	1	\$ 100.00	\$ 100.00
56	Check and Rectify Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 3,670.00
Estimate prepared by: KenGuan				
The above is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has been started. Worn or damaged parts are discovered which may not be evident on first inspection. Because of this,				
Amount Before Excess				\$ 4,230.00
Add GST @ 7%				296.10
Total Amount Payable				\$ 4,526.10