

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road  
Sime Darby Performance  
Singapore 159941  
Tel. 63190100 (Sale)  
63190111 (After)  
Fax. 64747770

280, Kampong Arang  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (Aft)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Tel. 63190528  
63190533/530  
Fax. 64796601  
64796624



## SERVICE TAX INVOICE

Repair Order No. : B1 1681541 Date IN : 04/08/2022 Motor Claim Advisor: Chua Kee Sin	Page No. : 1 of 2 Invoice Number : 2571653 / WSB Invoice Date : 23/09/2022 Payment Terms : 30 Days From Invoice Invoice By : Mahamod Bin Mohd Sanif																				
<b>- CUSTOMER INFORMATION -</b> Ms Tan Yong Leng Gillian 106 Pemimpin Terrace  Singapore 575990	<b>- INVOICE TO - 85</b> Liberty Insurance Pte Ltd 51 Club Street #03-00 Liberty House Singapore 069428																				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 20%;">REGN. NO.</td> <td style="width: 20%;">CHASSIS NO.</td> <td style="width: 20%;">REGN. DATE</td> <td style="width: 20%;">MODEL</td> <td style="width: 20%;">MILEAGE</td> </tr> <tr> <td>SMW1022E</td> <td>WBA6Y320707F66617</td> <td>30/10/2020</td> <td>225XE</td> <td>23591</td> </tr> </table>		REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE	SMW1022E	WBA6Y320707F66617	30/10/2020	225XE	23591										
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE																	
SMW1022E	WBA6Y320707F66617	30/10/2020	225XE	23591																	
<div style="display: flex; justify-content: space-between;"> <div> <p>----- L A B O U R 1 -----</p> <p>Replace both right door and attachments include knocking out dents caused by accident. <span style="float: right;">1,700.00</span></p> <p>Painting both right door, lower skirting right and both outer side handle <span style="float: right;">1,770.00</span></p> <p>To carry out body cavity preservation. (2 panel). <span style="float: right;">236.00</span></p> <p>To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (2 doors). <span style="float: right;">1,062.00</span></p> <p>To conduct water leak tests. <span style="float: right;">75.00</span></p> <p>Sundries. <span style="float: right;">80.00</span></p> <p>INS CLAIMS : ACCIDENT REPAIR, OD CLAIMS. <span style="float: right;">0.00</span></p> <p>DATE OF ACCIDENT : 30.07.22. POLICY NO : C0121633.</p> <p>YOUR REF NO : AVS22/2123.</p> <p>PAER SURVEY BY THINH FROM LIBERTY ON 02.08.22.</p> <p>AUTHORISED BY THINH VIA EMAIL ON 03.08.22.</p> <p>UNINSURED LOSSES HANDLED BY T.A AGAINST XX <span style="float: right;">0.00</span></p> <p>3RD PARTY CAR : YP8571K. INSURANCE EXCESS = \$3210.00</p> <p>PROPOSE LOSS OF USE = \$100X5 XXX SEARCH FEE = \$</p> </div> <div style="text-align: right;"> <p>Total Labour 1: <b>4,923.00</b></p> </div> </div> <div style="display: flex; justify-content: space-between; margin-top: 20px;"> <div> <p>----- P A R T S -----</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th></th> <th>Qty</th> <th>Retail Price</th> <th>NETT</th> </tr> </thead> <tbody> <tr> <td>RR RH DOOR <i>Dental</i></td> <td>1</td> <td>1,395.75</td> <td>1,395.75</td> </tr> <tr> <td>RH COVERING PRIMEND <i>Hec</i></td> <td>1</td> <td>48.75</td> <td>48.75</td> </tr> <tr> <td>FRT RH DOOR <i>Dental</i></td> <td>1</td> <td>1,130.75</td> <td>1,130.75</td> </tr> <tr> <td>RH DOOR OUTER HANDLE PRIMED <i>cut</i></td> <td>1</td> <td>97.45</td> <td>97.45</td> </tr> </tbody> </table> </div> <div style="text-align: right;"> <p>Total Parts : <b>2,672.70</b></p> </div> </div>			Qty	Retail Price	NETT	RR RH DOOR <i>Dental</i>	1	1,395.75	1,395.75	RH COVERING PRIMEND <i>Hec</i>	1	48.75	48.75	FRT RH DOOR <i>Dental</i>	1	1,130.75	1,130.75	RH DOOR OUTER HANDLE PRIMED <i>cut</i>	1	97.45	97.45
	Qty	Retail Price	NETT																		
RR RH DOOR <i>Dental</i>	1	1,395.75	1,395.75																		
RH COVERING PRIMEND <i>Hec</i>	1	48.75	48.75																		
FRT RH DOOR <i>Dental</i>	1	1,130.75	1,130.75																		
RH DOOR OUTER HANDLE PRIMED <i>cut</i>	1	97.45	97.45																		

5 days

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-00200

303, Alexandra Road  
Sime Darby Performance  
Singapore 159941  
Tel. 63190100 (Sale)  
63190111 (After)  
Fax. 64747770

280, Kampong Arang  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (Aft)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business  
Singapore 159944  
Tel. 63190528  
63190533/530  
Fax. 64796601  
64796622

**SERVICE TAX INVOICE**

Repair Order No. : B1 1681541

Date IN : 04/08/2022

Motor Claim Advisor: Chua Kee Sin

Page No. : 2 of 2

Invoice Number : 2571653 / WSB

Invoice Date : 23/09/2022

Payment Terms : 30 Days From Invoice

Invoice By : Mahamod Bin Mohd Sanif

Labour Charges : 4,843.00  
Parts Charges : 2,672.70  
Lubricant/Misc : 80.00

Total Labour & Parts Charges	: S\$	7,595.70
Less Insurance Excess	: S\$	3,000.00
Invoice Total Amount Exclude GST	: S\$	4,595.70
GST @ 7%	: S\$	321.70
Invoice Total Amount Include GST	: S\$	4,917.40

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 4,917.40

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

