

The Motor Claims Department
M/s Lonpac Insurance Bhd
300 Beach Road, #17-04/07
The Concourse
Singapore 199555

File No : SH/2022/282/10/037/OD
Date : 03-November-2022

Estimated cost of repair for vehicle no : SMN7385R Mitsubishi Attrage
Policy no: Z22VP05031844 Accident Date: 26.10.2022

Description	Quantity	Cost Price
Bonnet	1	\$ 350.00
LH Bonnet hinge	1	\$ 60.00
LH head lamp	1	\$ 280.00
LH front fender	1	\$ 240.00
LH front fender wheel cowling	1	\$ 70.00
Front fender wheel cowling clips (1 set)	1	\$ 15.00
LH front fender badge "ECO"	1	
LH front fender chrome trim	1	\$ 55.00
Front bumper	1	\$ 350.00
Front bumper clips (1 set)	1	\$ 15.00
Front bumper centre grille	1	\$ 280.00
Front bumper reinforcement	1	\$ 450.00
LH Front bumper fog lamp	1	\$ 190.00
LH Front bumper fog lamp cover	1	\$ 75.00
LH Front bumper retainer	1	\$ 20.00
LH Front bumper bracket	1	\$ 20.00
LH front ABS sensor	1	\$ 190.00
		\$ 2,660.00
	Add 15%	\$ 399.00
		\$ 3,059.00

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment \$ 650.00

To spray paint affected front and inner damaged portion inclusive of preparatory works and material \$ 850.00

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality \$ 50.00

To perform computer diagnostic on ABS systems, parking system, headlamp systems, and clear fault codes \$ 150.00

To perform computerised wheel alignment \$ 60.00

\$ 4,819.00