

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

LKK Auto Consultants hence notify
 the Repairer of the following:

- To display damaged part(s) during resurvey
- Paris prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Not Authorised
 3/11/22
 4 days 1/5 @ 6800

Vehicle Number: SND2075J

Vehicle Model: SKODA KODIAQ

PARTICULAR

AMOUNT

QTY

SS

LIST PRICE

1	FRONT BUMPER	Dis/torn	1850	\$ 2,175.00	✓
1	FRONT BUMPER SIDE GRILLE -RH	grnd/torn		\$ 195.00	✓
2	FRONT BUMPER PDC SENSOR @\$285	shold	225	\$ 570.00	IPC
1	FRONT BUMPER SPONGE	11		\$ 192.00	X
1	FRONT BUMPER REINFORCEMENT	11		\$ 1,075.00	X
2	FRONT BUMPER SIDE RETAINERS -R/L @\$65	o/s one		\$ 130.00	IPC
1	FRONT BUMPER LOWER SPOILER	grnd		\$ 835.00	✓
1	FRONT FENDER -RH	Body ID		\$ 1,055.00	✓
1	FRONT FENDER PROTECTOR	DJ		\$ 535.00	✓
1	FRONT FENDER INNER SHIELD	DJ		\$ 286.00	✓
1	FRONT FENDER STAY	11		\$ 115.00	X
1	FRONT FENDER EMBLEM	11		\$ 85.00	✓
1	FRONT HEADLAMP ASSY	holder one	3450	\$ 4,355.00	✓
1	FRONT SPORT WHEEL -RH	11		\$ 1,150.00	X
1	FRONT SHOCK ABSORBER -RH	11		\$ 695.00	X

\$ 13,448.00

LESS 10% \$ 1,344.80

\$ 12,103.20

8589
 102
 772.9

SPECIAL NETT ITEMS

1	(SET) FRONT BUMPER CLIP	111		\$ 60.00	50
1	(SET) FRONT FENDER PROTECTOR CLIP	11		\$ 60.00	X
1	(SET) FRONT FENDER INNER SHIELD CLIP	111		\$ 60.00	50
				\$ 180.00	

LABOUR CHARGES

TO CHECK FRONT ELECTRICAL WIRING		\$ 50.00	20
TO TUFF KOTE		\$ 60.00	30
TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	11	\$ 120.00	X
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$ 800.00	450
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		\$ 800.00	300
		\$ 1,830.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 14,113.20