

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

*Veron*

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623

**Estimate No:** EST2200354  
**Date:** 02 Nov 2022

TEL: 64616555 FAX: 62213147  
 ATTN: Motor Claim Department

Veh Reg No: **SJP7390A**  
 Make/Model: HONDA FIT 1.3G A  
 Chasis No: GE61158296  
 Reg. Date: 03/04/2009  
 Your Ref No: GZ4517E

Claim Type: Third Party  
 Accident Date: 01/11/2022  
 TP Veh Reg No: GZ4517E

## Estimate Repair Cost to Vehicle No :SJP7390A

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	<b>List Price</b>		
1	1 PC BOOT LID <i>Dented.</i>	881.50	✓
2	1 PC BOOT LID "FIT" EMBLEM <i>new</i>	35.00	✓
3	1 PC BOOT LID LOGO <i>new new</i>	25.00	✓
4	1 PC BOOT LID BLACK GARNISH <i>new cut</i>	134.10	✓
5	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	119.60	✓
6	1 PC REAR WINDSCREEN RUBBER <i>new</i>	125.50	✓
7	1 PC REAR WIPER ASSY <i>new</i>	135.20	+
8	1 PC REAR WIPER MOTOR <i>new</i>	488.00	+
9	1 PC BOOT LID LOCK <i>Disc</i>	189.00	✓
10	1 PC BOOT LID LOCK CHECKER <i>new</i>	34.50	+
11	1 PC BOOT LID RUBBER <i>cut</i>	162.40	✓
12	1 PC BOOT LID TRIM <i>Del'd</i>	189.30	✓
13	1 PC REAR PANEL <i>Dented</i>	376.50	✓
14	1 PC REAR PANEL TRIM <i>Del'd</i>	98.80	✓
15	1 PC REAR FENDER RH <i>Buckled</i>	785.20	✓
16	1 PC REAR FENDER RH SIDE GLASS <i>new</i>	366.70	+
17	1 PC REAR FENDER COWLING RH <i>new</i>	76.90	✓
18	1 PC REAR FENDER TRIM RH <i>Del'd</i>	386.80	✓ <i>295</i>
19	1 PC REAR FENDER TRIM LH <i>Del'd</i>	386.80	✓ <i>295</i>
20	1 PC REAR FENDER TOP TRIM RH <i>new</i>	278.60	+
21	1 PC SPARE TYRE PANEL <i>Buckled</i>	787.00	✓
22	1 PC REAR SPARE TYRE PANEL SPONGE <i>Del'd</i>	280.80	✓
23	1 PC REAR SPARE TYRE PANEL HARDBOARD <i>coupled</i>	321.90	✓
24	1 PC TAIL LAMP LH <i>cut</i>	288.60	✓
25	1 PC TAIL LAMP PANEL RH <i>Repl Dented</i>	233.60	✓
26	1 PC TAIL LAMP - RH <i>coupled</i>	288.20	✓
27	1 PC REAR BUMPER <i>Del'd</i>	525.50	✓
28	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	86.00	✓
29	1 PC EXHAUST PIPE <i>Best</i>	682.30	✓
	1 pc Ventilation <del>gas</del> air duct <i>Del'd</i>	38	✓

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623

Estimate No: EST2200354  
 Date: 02 Nov 2022

TEL: 64616555 FAX: 62213147  
 ATTN: Motor Claim Department

Veh Reg No: SJP7390A  
 Make/Model: HONDA FIT 1.3G A  
 Chasis No: GE61158296  
 Reg. Date: 03/04/2009  
 Your Ref No: GZ4517E

Claim Type: Third Party  
 Accident Date: 01/11/2022  
 TP Veh Reg No: GZ4517E

## Estimate Repair Cost to Vehicle No :SJP7390A

Quantity	Description	List Price	Amount
30	4 PCS EXHAUST PIPE MOUNTING <i>1 pieces damaged</i>	7518.90	<del>156.80</del> <i>39.20</i> SS
31	1 PC REAR EXHAUST HEAT SHIELD <i>crushed</i>	6015.12	<del>199.70</del> <i>95</i>
32	1 PC CENTRE EXHAUST PIPE <i>Not in</i>		<del>799.20</del> X
			9.925.00
		Less 20%	1.985.00 7.940.00
	<b>Special Net</b>		
33	1 PC REAR NUMBER PLATE <i>Dented</i>		50.00 ✓
34	1 PC REAR WINDSCREEN SEAL <i>green</i>		<del>60.00</del> <i>30</i>
35	1 PC REAR WINDSCREEN SEALANT <i>green</i>		<del>60.00</del> <i>30</i>
36	1 SET BOOTLID TRIM CLIPS <i>per</i>		<del>40.00</del> <i>30</i>
37	1 SET REAR PANEL TRIM CLIPS <i>in</i>		<del>30.00</del> <i>20</i>
38	1 PC REAR FENDER RH SIDE GLASS SEALANT <i>in</i>		<del>60.00</del> <i>30</i>
39	1 PC FENDER RH SIDE GLASS INNER SEAL <i>in</i>		<del>60.00</del> X
40	1 SET REAR FENDER COWLING CLIPS RH <i>in</i>		<del>30.00</del> X
41	1 SET REAR FENDER TRIM CLIPS RH <i>green</i>	<i>600</i>	<del>40.00</del> <i>30</i>
42	1 SET REAR FENDER TRIM CLIPS LH <i>green</i>		<del>40.00</del> <i>30</i>
43	1 SET REAR FENDER TOP TRIM CLIPS RH <i>in</i>		<del>40.00</del> X
44	1 SET REAR BUMPER CLIPS <i>in</i>		<del>40.00</del> <i>30</i>
45	1 SET REVERSE SENSORS <i>2nd</i>		<del>300.00</del> <i>20</i>
46	1 PC JACK <i>Not in</i>		<del>300.00</del> X
	<i>1 set Rear End Panel Sealant. green</i>	<i>100.60</i>	300.00 X
	<i>1 set Rear Fender Sealant</i>	<i>100.60</i>	1.150.00 1.150.00
	<b>Labour</b>		
47	1 TO CHECK WIRING		<del>50.00</del> <i>30</i>
48	1 TO REMOVE AND REFIT: <i>bootlid fittings.</i>		<del>80.00</del> ✓
49	1 TO REMOVE AND REFIT REAR WINDSCREEN		<del>120.00</del> ✓
50	1 TO REMOVE AND REFIT RH FENDER GLASS		<del>100.00</del> <i>50</i>
51	1 TO REMOVE AND REFIT REVERSE SENSOR		<del>80.00</del> <i>50</i>
52	1 TO REMOVE AND REFIT INNER TRIM		<del>180.00</del> <i>80</i>
53	1 TO REMOVE AND REFIT REAR & CENTRE EXHAUST PIPE		<del>280.00</del> <i>80</i>
54	1 TO SPRAY PANEL SEALANT		<del>150.00</del> <i>60</i>

# Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883  
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg  
 GST:201300201N

**M/S :** SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PLACE  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623

TEL: 64616555 FAX: 62213147  
 ATTN: Motor Claim Department

Claim Type: Third Party  
 Accident Date: 01/11/2022  
 TP Veh Reg No: GZ4517E

**Estimate No:** EST2200354  
**Date:** 02 Nov 2022

Veh Reg No: **SJP7390A**  
 Make/Model: HONDA FIT 1.3G A  
 Chasis No: GE61158296  
 Reg. Date: 03/04/2009  
 Your Ref No: GZ4517E

## Estimate Repair Cost to Vehicle No :SJP7390A

Quantity	Description	List Price	Amount
55	1 (REAR) TO SPRAY PAINTING	<del>1,600.00</del> 3650- 1400	<del>SS</del> SS
56	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	<del>2,000.00</del> 1700	<del>SS</del> SS
		4,640.00	4,640.00
		Total	S\$ 13,730.00
		Add GST @ 7%	961.10
		Total Amount Payable	<u>S\$ 14,691.10</u>

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND SIX HUNDRED NINETY ONE AND CENTS TEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian G  
 A/S 03/11/22

12 Days.

Total: 10265.12

A/S: 8.2K.

8.2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: