

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010993/UVP3Q2**Date:** 09/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00117842200

Claimant Vehicle No : FBR3074Z **Insured Vehicle No :** SDN19B

Date of Loss: 31/10/2022 Nature of Claim: TP Claim No: SNM22D207853/C02/ALFRED

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR3074Z**

Make & Model: HONDA ADV750, 745cc ABS AUTO Engine No: KF61E1018026

Reg. Date: 04/04/2020 (Man. Year: 2020) Chassis No: MH1KF6113KK018074

Colour: Red Odometer: 71564 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-14 Rear Tyre Size: 130/70-13

Front Left Side: Pirelli 6 mm Rear Left Side: MITAS 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,243.00	758.70	2,484.30	76.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	200.00	780.00	79.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,223.00	958.70	3,264.30	77.30
Approved Total (Overridden) (\$\$)		750.00		
Nett Amount (\$\$)	4,223.00	750.00	3,473.00	82.24

INSPECTION

Date of Assignment: 03/11/2022

Date Inspected: 04/11/2022 Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Nov 2022)	
Parts:	N/A	HONDA ADV750 745cc ABS AUTO (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR3074Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	168.00 FL	*128.00 FL
2	2		*FRONT FORK TUBE ASSY	Not Necessary	680.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	220.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	125.00 FL	*- FL
5	1		*SET FRONT SIGNAL	Not Necessary	216.00 FL	*- FL
6	1		*HANDLE BAR	Not Necessary	180.00 FL	*- FL
7	1		*SET HANDLE BAR BALANCER	Not Necessary	98.00 FL	*- FL
8	1		*SET HAND GRID	Not Necessary	58.00 FL	*- FL
9	1		*MIRROR	Not Necessary	110.00 FL	*- FL
10	1		*BRAKE LEVER	Not Necessary	130.00 FL	*- FL
11	1		*FOOT STEP PANEL -L/H	Cut	160.00 FL	*155.00 FL
12	1		*FOOT STEP LOWER PANEL -L/H	Cut	180.00 FL	*170.00 FL
13	1		*FRONT SIDE FAIRING -L/H	Cut	190.00 FL	*140.00 FL
14	1		*SET FOOT STEP PROTECTOR	Bent	385.00 FL	*250.00 FL
15	1		*SIDE STAND	Not Necessary	165.00 FL	*- FL
16	1		*MAIN STAND	Not Necessary	225.00 FL	*- FL
17	1		*REAR FOOTREST	Not Necessary	70.00 FL	*- FL
18	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
19	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
21	1		*BEARING CONE	Not Necessary	95.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,579.00	843.00
- List Item Discount on L Items 10.00/10.00% (\$)	336.00	84.30
Total Parts (\$)	3,243.00	758.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO RESPRAY PAINT	New	420.00	0.00
3	TO PROVIDE LABOUR	New	480.00	200.00
Gross Labour Cost (\$\$)			980.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >