

ASS. REC'D. BY:

REF:

A15 / 220109941Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

881K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

1. B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 1426L

Yr Regn:

03.19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

c.c

1591

Colour

M. D. Blue

A/C:

Insured / Std / Nil / NA

Sp. Reading

65138

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

KM14D 841CMK4 880698

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / ARM or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

9

mm

R/Bal.

5

mm

L/Bal.

9

mm

L/Bal.

5

mm

D.O.A.

1/11/22

D.O.I.

4/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/11/21 Rm @ 2230h Calw 10/11/23

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Allianz Insurance Singapore Pte. Ltd.**
79, Robinson Road, #09-01,
Singapore 068897

Attn : Motor Claims Department
Tel : 67143369
Fax : 62971956

Estimate bill : TT 40 / 22 / TP / WT

Registration No : SMK1426L

Make / model : Hyundai Avante

Mileage :

Date : 02 / 11 / 2022

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK1426L, SML6340L AND SLF9535R ALONG UPPER SERANGOON ROAD ON 01 NOVEMBER 2022 AT ABOUT 0756HRS.

1pc	Rear boot emblem		\$	nn	41.00	X
1pc	Rear boot 'Avante' designation		\$	nn	49.00	X
	Rear boot hinge	(Each \$81.00)	\$	n	162.00	X
2pcs	Rear tail lamp (LH)	(Each \$715.00)	\$	nn	1,430.00	X
	Rear end panel		\$	Rn	405.00	✓
1pc	Rear bumper	489.80	\$	Bu	594.00	✓
1set	Rear bumper parking sensor		\$	Shor	280.00	Wola
1pc	Rear license plate garnish		\$	nd	41.00	✓
1pc	Rear bumper lip	340.60	\$	Bu	486.00	✓
1pc	Rear bumper lip fog lamp (LH)	@201.50	\$	nl's cm	486.00	✓
2pcs	Rear bumper side retainer	(Each \$49.00)	\$	clm	98.00	✓
1pc	Rear bumper reinforcement	329.60	\$	cm	440.00	✓
3pcs	Rear bumper reinforcement bracket (Top)	(Each \$17.00)	\$	cm	68.00	✓
2pcs	Rear bumper reinforcement bracket (Bottom)	(Each \$11.00)	\$	cat	22.00	✓
1pc	Rear antenna reveiver		\$	nn	68.00	X
	Sub A total :		\$		4,670.00	
	Less 20% discount :		\$		934.00	
	C total :		\$		3,736.00	
Special net items :						
1pc	Rear license smart plate & casing		\$	Rn	40.00	✓
	D total :		\$		40.00	
Total amount of Page 2 :			\$		3,776.00	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Not Authorised
Resurvey B4 painting
4 days
L1 Lmp @ 2250h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **Allianz Insurance Singapore Pte. Ltd.**
79, Robinson Road, #09-01,
Singapore 068897

Estimate bill : TT 40 / 22 / TP / WT

Registration No : SMK1426L

Attn : Motor Claims Department
Tel : 67143369
Fax : 62971956

Make / model : Hyundai Avante

Mileage :

Date : 02 / 11 / 2022

TRAFFIC CHAIN ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK1426L, SML6340L AND SLF9535R ALONG UPPER SERANGOON ROAD ON 01 NOVEMBER 2022 AT ABOUT 0756HRS.

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot emblem, rear boot 'Avante' designation, rear boot hinges, rear tail lamps, rear bumper, rear bumper parking sensors, rear license plate garnish, rear bumper lip, rear bumper lip fog lamps, rear bumper side retainers, rear bumper reinforcement, rear bumper reinforcement brackets (Top), rear bumper reinforcement brackets (Bottom), rear antenna receiver.

Heat / weld / cut / renew rear end panel, heat / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot hinges, rear end panel, rear bumper, rear bumper parking sensors, rear bumper lip.

Balance amount brought from Page 1 :

Grand final amount :

\$ 1,000.00 *600*

\$ 100.00 *500*

\$ 80.00 *150*

\$ 200.00 *300*

\$ 1,200.00 *400*

\$ 3,776.00

\$ 6,356.00

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

