



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 592J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	MIRROR @\$130.00	CUT (1 PCS ONLY)	260.00	150.00
1	ENGINE GUARD	CUT	190.00	190.00
1	HANDLEBAR	NOT NECESSARY	280.00	-
1	REAR RIM	NOT NECESSARY	1,100.00	-
1	NUMBER PLATE	BENT	40.00	40.00
1	FRAME SLIDER	CUT	220.00	135.00
1	SIDE STAND	SCRATCHED	190.00	115.00
	LESS 10% DISCOUNT		-	-63.00
			2,280.00	567.00
	<u>LABOUR</u>			
	LABOUR .		200.00	200.00
	FORK PRESS.		180.00	90.00
			380.00	290.00
	GRAND TOTAL		2,660.00	857.00
	RECOMMENDED COST OF REPAIR SUM			850.00

Report Ref No. CS/AGI22010996/Sqy3q2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.