

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0963/2022/EQ
DATE : 4-Nov-22
WIP : 48975

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/11/2022

YOUR INSURED VEH NO : SJC 3158 A

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

Hi Adrian

3 days - ok - Johnny Boo

27-Dec-22

OWNER'S NAME : MR LAM PIK WAN
ADDRESS : 30 LOYANG RISE
SINGAPORE 507571

TELEPHONE : HP +65 90303896
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5110147973-03
VEHICLE NO : **SLD 9382 A**
MODEL CODE : AUDI A3 CABRIOLET 1.4 TFS
MODEL YEAR : 30/6/2016
ENGINE NO : CZC 564521
CHASSIS NO : WAUZZZ8V3G1104646
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Nov-22
PLACE OF ACCIDENT : FARRER ROAD TOWARDS DUNEARN ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 9382 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 700.00
3	TO RESPRAY REAR BUMPER.	\$	900.00	\$ 700.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	2,422.00	\$ 1,872.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 9382 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,201.00	\$ 2,201.00
2	REAR BUMPER FIXING PARTS	1	\$ 201.00	
3	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	
4	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 67.00	
5	REAR BUMPER SPOILER	1	\$ 264.00	\$ 263.50
6	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00	
8	REAR BUMPER BRACKET - LH / RH	2	\$ 30.00	
9	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
10	REAR PARKING AID SEAL RING	4	\$ 10.00	
11	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS			\$ 4,474.00	\$ 2,464.50
TOTAL LABOUR CHARGES			\$ 2,422.00	\$ 1,872.00
GRAND TOTAL			\$ 6,896.00	\$ 4,336.50

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-20/12/22



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT