

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

**Our File No:** CS6/AIS22011001/TQY3E2**Date:** 29/12/2022**REFERENCE**

Insured/Claimant:	SIEM TRADING PTE LTD	Policy No:	SP2002553878-01	
Date of Loss:	29/10/2022	Nature of Claim:	OD	Claim No: 202222007834

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGE5576M</b>		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	2ZR1522238
Reg. Date:	16/03/2015 (Man. Year: 2015)	Chassis No:	JTDGG20W00J002268
Colour:	Gold	Odometer:	190264 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$46,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,753.00	3,723.00	30.00	0.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,570.00	700.00	30.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,023.00</b>	<b>5,293.00</b>	<b>730.00</b>	<b>12.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,250.00</b>		
<b>(S\$)</b>	6,023.00	4,250.00	1,773.00	29.44
<b>+ GST 7.00/7.00% (S\$)</b>	421.61	297.50	124.11	29.44
<b>Nett Amount (S\$)</b>	<b>6,444.61</b>	<b>4,547.50</b>	<b>1,897.11</b>	<b>29.44</b>

**INSPECTION**

Date of Assignment:	03/11/2022	Present Location:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected:	03/11/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-06, Sin Ming Autocare Singapore 575721
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2022)
<b>Parts:</b>	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGE5576M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH Front Fender (WCP)	Bent	350.00 F	*350.00 F
2	1		*RH Side Mirror (WCP)	Distorted	385.00 F	*385.00 F
3	1		*RH Front Door (WCP)	Bent	680.00 F	*680.00 F
4	1		*RH Front Door Black Tape (WCP)	Necessary	90.00 F	*90.00 F
5	1		*RH Front Door Chrome (WCP)	Cut	280.00 F	*280.00 F
6	1		*RH Side Skirt (WCP)	Cracked	480.00 F	*480.00 F
7	1		*RH Front Sports Rim	Dented	800.00 FS	*800.00 FS
8	1		*RH Front Fender Shield (WCP)	Torn	145.00 F	*145.00 F
9	1		*RH Front Fender Shield Clip	Necessary	60.00 FS	*30.00 FS
10	1		*RH Front Door Hinge Top (WCP)	Bent	110.00 F	*110.00 F
11	1		*RH Front Door Hinge Bottom (WCP)	Bent	110.00 F	*110.00 F
					<b>Sub Total (\$\$)</b>	<b>3,490.00 3,460.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>263.00 263.00</b>
					<b>Total Parts (\$\$)</b>	<b>3,753.00 3,723.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To transfer RH front door parts	New	100.00	60.00
2	To transfer tyre to new rim and balancing	New	50.00	30.00
3	Computerise wheel alignment	New	120.00	80.00
4	To repair front door pillar including replacement of parts	New	700.00	500.00
5	To spray paint on front bumper, RH side mirror, RH front fender, RH front door, RH front door pillar, RH side skirt	New	1,300.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>2,270.00</b>	<b>1,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >