

ASS. REC. BY: T. J. M.

REF: CS6/MS 2201/001/TQ 43.

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

☒ TP / ☐ IS / TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 100 0/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$46K.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5 days

Res.: Yes or No

Lum Sum: _____ %

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 84E 5576M

Yr Regn: 2015 / March

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Wish

c.c. 1798

Colour: Gold

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 190264

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: STD6620W005*002268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55 R16

R: 7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm

mm

R/Bal. 6 mm

mm

L/Bal. 6 mm

mm

L/Bal. 6 mm

mm

D.O.A. _____

D.O.I. _____

Survey held at Falcon Urv

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Steve finalised LS \$4250, 5 days. (Red \$1773, 29%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/12 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS. \$ _____

Photos

Others

Report Form: MER-OD

Lum Sum / LS: 4250



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002553878-01	Date of Loss:	29/10/2022
Vehicle Reg. No.:	SGE5576M	Driveable?	
Driver Age/Info:	58 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIEM TRADING PTE LTD		
Driver:	CHAI KIEW CHAI		
Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	16/03/2015
Vehicle Colour:	RED		
Engine No:	2ZR1522238	Chassis No:	JTDGG20W00J002268
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO SAS REPORT		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	3,753.00
Miscellaneous Items	0.00
Labour	2,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,023.00
+ GST 7.00% (S\$)	421.61
Nett Amount (S\$)	6,444.61

This claim is handled by: ANDY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 03 Nov 2022)**Parts:** M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH Front Fender	0.00	0.00	*350.00 F <i>ht</i> ✓
2	1		*RH Side Mirror	0.00	0.00	*385.00 F <i>dis</i> ✓
3	1		*RH Front Door	0.00	0.00	*680.00 F <i>ht</i> ✓
4	1		*RH Front Door Black Tape	0.00	0.00	*90.00 F <i>nc</i> ✓
5	1		*RH Front Door Chrome	0.00	0.00	*280.00 F <i>mt</i> ✓
6	1		*RH Side Skirt	0.00	0.00	*480.00 F <i>eng</i> ✓
7	1		*RH Front Sports Rim	0	0.00	*800.00 FS <i>dd</i> ✓
8	1		*RH Front Fender Shield	0.00	0.00	*145.00 F <i>fn</i> ✓
9	1		*RH Front Fender Shield Clip	0	0.00	*60.00 FS <i>nc</i> ✓ 30
10	1		*RH Front Door Hinge Top	0.00	0.00	*110.00 F ?
11	1		*RH Front Door Hinge Bottom	0.00	0.00	*110.00 F ?

F=Franchise part. S=SpcNett.

Sub Total (\$\$)**3,490.00****+ Margin on L,N Items 10.00% (\$\$)****263.00****Total Parts (\$\$)****3,753.00****Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01. Not valid without Reference section.**

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To transfer RH front door parts	New	100.00 60
2	To transfer tyre to new rim and balancing	New	50.00 30
3	Computerise wheel alignment	New	120.00 80
4	To repair front door pillar including replacement of parts	New	700.00 500
5	To spray paint on front bumper, RH side mirror, RH front fender, RH front door, RH front door pillar, RH side skirt	New	1,300.00 900
Gross Labour Cost (S\$)			2,270.00

Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7852
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Taufik 97495449
Not Authorise 2/11/22
Ex: to be advise
Lumpsum Resurvey after repair
taufik@lkhauto.com
55 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: