

ACC. REC. BY: T. J. M.

REF: CS6/MS 2201/001/TQ 43.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / ☐ VS / TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: 169

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$46K.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: 84E 5576M

Yr Regn: 2015 / March

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Wish

c.c. 1798

Colour: Gold

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 190264

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: STD6620W005*002268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55 R16

R: 7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. _____

Survey held at

Falcon Urv

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

S + RS. \$ _____

Photos _____

Others _____

Report Form: _____

Lum Sum / B. C. P. _____



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. No.: 1995-01140-D

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002553878-01	Date of Loss:	29/10/2022
Vehicle Reg. No.:	SGE5576M	Driveable?	
Driver Age/Info:	58 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SIEM TRADING PTE LTD		
Driver:	CHAI KIEW CHAI		
Make/Model:	TOYOTA WISH, 1.8 CVT (A)	Vehicle Reg. Date:	16/03/2015
Vehicle Colour:	RED		
Engine No:	2ZR1522238	Chassis No:	JTDGG20W00J002268
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO SAS REPORT		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	3,753.00
Miscellaneous Items	0.00
Labour	2,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,023.00
+ GST 7.00% (S\$)	421.61
Nett Amount (S\$)	6,444.61

This claim is handled by: ANDY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Nov 2022)

Parts: M1-MPV TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH Front Fender	0.00	0.00	*350.00 F ht✓
2	1		*RH Side Mirror	0.00	0.00	*385.00 F dis✓
3	1		*RH Front Door	0.00	0.00	*680.00 F ht✓
4	1		*RH Front Door Black Tape	0.00	0.00	*90.00 F net✓
5	1		*RH Front Door Chrome	0.00	0.00	*280.00 F int✓
6	1		*RH Side Skirt	0.00	0.00	*480.00 F en✓
7	1		*RH Front Sports Rim	0	0.00	nett *800.00 FS dd✓
8	1		*RH Front Fender Shield	0.00	0.00	*145.00 F fu✓
9	1		*RH Front Fender Shield Clip	0	0.00	nett *60.00 FS net✓ 30
10	1		*RH Front Door Hinge Top	0.00	0.00	*110.00 F ? ✓ BT
11	1		*RH Front Door Hinge Bottom	0.00	0.00	*110.00 F ? ✓ BT

F=Franchise part. S=SpcNett.

2630
+10%
2893

830

Sub Total (S\$)

3,490.00

+ Margin on L,N Items 10.00% (S\$)

263.00

Total Parts (S\$)

3,753.00

Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To transfer RH front door parts	New	100.00 60
2	To transfer tyre to new rim and balancing	New	50.00 30
3	Computerise wheel alignment	New	120.00 80
4	To repair front door pillar including replacement of parts	New	700.00 500
5	To spray paint on front bumper, RH side mirror, RH front fender, RH front door, RH front door pillar, RH side skirt	New	1,300.00 900
1570			
Gross Labour Cost (\$)			2,270.00

Falcon-Air Auto Services Pte Ltd/SGE5576M/03/11/2022 11:01. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5293

L/S - 4234.40
= 4250

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7852
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Taufik 97495449
Not Authorise 2/11/22
Ex: to be advise
Lumpsum Resurvey after repair
taufik@lkkauto.com
55 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: