



## Final Report

Estimate No. : **b1 63881**  
Date Estimated : **02/11/2022**  
Prepared By : **Han Kwan Yong**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Harpal Singh**  
**Apt Blk 583 Woodlands Drive 16**  
**#02-462**

**Singapore 730583**

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SNF7827M</b>	<b>WBA6V720005U68411</b>	<b>22/06/2022</b>	<b>218i Gran Tourer</b>	<b>17</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear LH door and attachments include making good the rear LH fender and knocking out dents caused by the accident	1,275.00		1,275.00
* To spray paint rear LH door and rear LH fender	1,681.00		1,681.00
To carry out body cavity preservation (Per panel)	112.00		112.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function (x1)	504.00		504.00
To check electrical wiring system and lighting including reset and check air bag for proper function	280.00		280.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR LH DOOR	1,159.75	1.00	0.00	1,159.75
LH SEALING COLUMN B BOTTOM	57.90	1.00	0.00	57.90
REAR DOOR JOINT SEAL	34.05	1.00	0.00	34.05

**# SUPPLEMENTARY ITEMS**

Total Labour :	3,932.00
Total Parts :	1,251.70
Total Labour & Parts :	5,183.70
Deduction for Excess :	
Total Repair Costs less Excess:	5,183.70
GST @7%:	362.86
Grand Total :	5,546.56

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

