

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011004/UWP3E2
Date: 09/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00092702201
Claimant Vehicle No :	SNC8784L	Insured Vehicle No :	SML4519C
Date of Loss:	31/10/2022	Nature of Claim: TP	Claim No: SNM22D207863/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC8784L	Engine No:	1NZR417440
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKD3B3601588597
Reg. Date:	17/01/2017 (Man. Year: 2016)	Odometer:	74556 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,070.10	5,553.80	6,516.30	53.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,560.00	2,200.00	2,360.00	51.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,630.10	7,753.80	8,876.30	53.37
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	16,630.10	6,200.00	10,430.10	62.72

INSPECTION

Date of Assignment:	04/11/2022	
Date Inspected:	03/11/2022	Inspected At: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2022)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC8784L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER GARNISH	Not Necessary	138.50 FL	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.20 FL	*110.00 FL
3	1		*REAR TAILGATE	Badly Dented	1,000.30 FL	*1,000.30 FL
4	2		*REAR TAILGATE DAMPERS	Not Necessary	600.40 FL	*- FL
5	1		*REAR TAILGATE INNER BOARD	Deformed / Torn	252.00 FL	*252.00 FL
6	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	68.00 FL	*- FL
7	1		*REAR TAILGATE LOCK	Damaged / Shorted	452.00 FL	*385.00 FL
8	1		*REAR TAILGATE LOGO	Necessary	100.20 FL	*86.50 FL
9	1		*REAR TAILGATE OUTER CHROME MOULDING	Not Necessary	285.00 FL	*- FL
10	1		*REAR TAILGATE RUBBER	Twisted	360.00 FL	*298.40 FL
11	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	100.40 FL	*78.80 FL
12	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	92.00 FL	*68.50 FL
13	1		*HYBRID SYNERGY DRIVE EMBLEM	Necessary	90.90 FL	*80.60 FL
14	1		*REAR WIPER ARM	Not Necessary	150.20 FL	*- FL
15	1		*REAR WIPER MOTOR	Not Necessary	288.50 FL	*- FL
16	2		*REAR TAILLAMPS	Cracked	1,090.00 FL	*1,090.00 FL
17	1		*REAR END PANEL	Badly Dented	788.70 FL	*566.90 FL
18	1		*REAR END PANEL INNER GARNISH	Twisted	180.00 FL	*180.00 FL
19	1		*REAR KEYLESS SENSOR	Shorted / Cracked	195.00 FL	*195.00 FL
20	1		*REAR BUMPER	Distorted	999.70 FL	*792.10 FL
21	2		*REAR BUMPER BRACKETS	Bent	140.00 FL	*140.00 FL
22	1		*REAR BUMPER INNER SPONGE	No such part	110.50 FL	*- FL
23	1		*REAR BUMPER LOWER UNDERCOVER	Torn	552.00 FL	*165.70 FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	333.50 FL	*333.50 FL
25	2		*REAR BUMPER SIDE RETAINERS	Bent	150.40 FL	*150.40 FL
26	2		*REAR BUMPER TOP BRACKETS	Not Necessary	440.00 FL	*- FL
27	2		*REAR NUMBER PLATE LAMPS	Not Necessary	144.00 FL	*- FL
28	1		*REAR SPARE TYRE BOARD	Warped	543.60 FL	*543.60 FL
29	1		*REAR SPARE TYRE PANEL	Repair	1,217.20 FL	*- FL
30	2		*REAR SPARE TYRE SIDE BOARDS	Not Necessary	776.00 FL	*- FL
31	1		*REAR SPARE WHEEL RETAINER	Not Necessary	89.00 FL	*- FL
32	1		*REAR EXHAUST SILENCER	Not Necessary	1,173.00 FL	*- FL
33	2		*REAR EXHAUST MOUNTINGS	Not Necessary	160.20 FL	*- FL
34	1		*REAR FENDER INNER TRIMS	N/S Torn	1,377.40 FL	*461.10 FL
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*SET REAR TAILGATE INNER BOARD CLIP	Necessary	60.00 FS	*40.00 FS
37	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
38	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
39	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
40	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,726.80** **7,298.40**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					3,656.70	1,744.60
Total Parts (S\$)					12,070.10	5,553.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	200.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	200.00	0.00
7	TO APPLY UNDERCOATING	New	200.00	60.00
8	PANEL BEATING	New	1,800.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,560.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >