



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428		Ref: CS/LIP22011009/Rqy3e2 Date: 03/01/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SLV 372T	Veh. Inspected	GY 1275C
Policy No.		Coverage (\$)	0.00
Claim No.	BVS22/0559	Excess (\$)	0.00
Assign From	ESTHER CHEAH	Assign Date	03/11/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA 150D	c.c	2986
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JTFUF34Y103010026	Colour	GREY
Odometer	938924 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185 R14C	FALKEN	7 mm
L/H Front Tyre	185 R14C	FALKEN	7 mm
R/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm
L/H Rear Tyre	155 R12C (D)	FALKEN	5/5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	22/06/2022	Inspection Date	14/11/2022
Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)REGISTRATION DATE: 06 JAN 2005 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	