



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2301659

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/03/2023
Reference CC3/CTI22011014/Tya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3832K
Insured Veh. SNC 3839X
Claim No. SNM22D207754/C02
Policy No. DMPCSNW00239002100
Accident Date 28/10/2022
Inspection Date 31/10/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22011014/Tya3q2 Date: 17/03/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNC 3839X	Veh. Inspected	SHC 3832K
	Policy No.	DMPCSNW00239002100	Coverage (\$)	0.00
	Claim No.	SNM22D207754/C02	Excess (\$)	0.00
	Assign From		Assign Date	31/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVLU188165	Colour	BLUE
	Odometer	211987 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/10/2022	Inspection Date	31/10/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3832K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY	CRACKED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER BEAM	NOT NECESSARY	394.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	ANTENNA SMARTKEY	NECESSARY	40.50	40.50
1	FOG LAMP	CRACKED	201.50	201.50
2	NUMBER PLATE LAMP (LH/RH) @\$85.30	NOT NECESSARY	170.60	-
1	REAR UNDER LOWER COVER	DEFORMED	155.00	155.00
1	REAR UNDER CENTRE UNDER COVER	NOT NECESSARY	225.00	-
1	TOW COVER	NOT NECESSARY	98.80	-
1	BOOT LAMP ASSY RH	NOT NECESSARY	822.00	-
	LESS 20% DISCOUNT		-608.17	-265.93
			2,432.68	1,063.72
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	REVERSE SENSOR (SN)	NOT WORKING	180.00	180.00
1	ADVERTISEMENT LOGO -FENDER (SN)	NOT NECESSARY	200.00	-
			430.00	230.00
	<u>LABOUR</u>			
	PANEL BEATING .		1,200.00	350.00
	SPRAY PAINT.		600.00	250.00
	REMOVE/REFIX REVERSE SENSOR .		50.00	30.00
	CHECK WIRING .		50.00	30.00
			1,900.00	660.00
	GRAND TOTAL		4,762.68	1,953.72

Report Ref No. CC3/CTI22011014/Tya3q2



RECOMMENDED COST OF REPAIRS			1,953.72
-----------------------------	--	--	-----------------

Report Ref No. CC3/CTI22011014/Tya3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3832K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3832K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3832K

RE-INSPECTION

