

**COMFORTDELGRO
ENGINEERING**

Our Job Ref No : 305534760

Date 22.11.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. SHC3832K

Date of Accident : 28.10.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SNC3839X
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,293.72
 - (b) Labour Charges \$660.00
 - Total for Part-By-Part Repair Cost \$1,953.72**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 27/12/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305534760
 REGN NO : SHC3832K
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 28.10.2022 16:00
 ACCIDENT DATE : 28.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004 04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00	161.20
0005 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00
0006 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00
0007 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	0.20	50.00
0008 09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40

SUB-TOTAL : 1,293.72

JOB NATURE

0000 L	PANEL BEAT(SHC3832K)TP	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 17-01	CHECK ALL LIGHTING	30.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305534760
REGN NO : SHC3832K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 28.10.2022 16:0
ACCIDENT DATE : 28.10.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 L REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL : 660.00

TOTAL : 1,953.72

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :