

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC7172E

01.11.2022

MAKE REG 07.04.2016

MODEL HYU- 140

Type

CHIANG/ MID

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER COVER <i>✓</i>		\$553.00
1	REAR BUMPER LOWER COVER <i>x</i>		\$228.00
1	REAR REINFORCEMENT <i>x</i>		\$428.40
10	REAR BUMPER CLIPS <i>✓</i>	\$2.20	\$22.00
2	REAR BUMPER BRACKET LH/RH <i>x</i>	\$35.60	\$71.20
2	REAR BUMPER REFLECTOR LH/RH <i>x</i>	\$32.00	\$64.00
	<b>SUB TOTAL</b>		<b>\$1,366.60</b>
	<b>20.00%</b>		<b>\$273.32</b>
	<b>DISCOUNTED TOTAL</b>		<b>\$1,093.28</b>
1	REAR BUMPER MAT <i>✓</i>		\$50.00
1	REAR REVERSE SENSOR <i>✓</i>		\$135.70
			<b>\$185.70</b>
	<b>Labour Charge</b>		
	Panel Beating		\$450.00
	Spray Painting Charge		\$300.00
	Remove/refix reverse sensor		\$60.00
	Check Lighting & Wiring		\$40.00
	<b>TOTAL LABOUR</b>		<b>\$850.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$2,128.98</b>
This is an initial estimate based on a visual inspection of the <u>above vehicle</u> . The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Days.  
4/5

Good Qit

4/11

12:30 pm

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts in marked tray
- Parts price to be on "market" basis
- Third party to be on "market" basis
- No ill will to be shown
- Supplier to be on "market" basis and is subject to the insurance company

Acknowledged by Repaired:

Signature:

Date: