

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 02/11/2022

User ID : JeongCH

Section A - Accident Details

Registration Number	SQ5576K
Case Reference Number	BUS/10/22/5036
Registration Date	11/29/2016
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Ang Zhan Zong
Type of Accident	Side Swipe
Accident Date and Time	10/28/2022 5:25 PM
Accident Reported Date and Time	11/1/2022 11:59 AM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SQ5576K - Front right bumper cracked and dislodged SMJ230X (TP) - Insured with Income
Prepared Date and Time	11/2/2022 1:45 PM
Chassis Number	YV3S4P924GA179515
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$956.00	\$0.00
Total Spare Part Cost	\$4,823.30	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,369.30	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	02/11/2022 1:56 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

PKK Auto Collision Centre notice
The Repairer of the following:
- To remedy defective repair being
- To rectify damaged body(s) during warranty
- Repair costs are subject to confirmation
- Third party survey is a "Without Prejudice" basis
- No liability (modifications) is allowed
- Repairer's liability is not to be transferred
- Subject to final approval from Insurance Company

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 02/11/2022

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,590.00	1060
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$956.00	786
Total Spray Painting & Panel Beating	\$956.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOVE, FRONT LOWER, CLASS 2, FOR VOLVO B9TL	1.00	\$3,391.95	0.00	\$3,391.95	Replace	Repair XR
	Body	ATP-02804	O/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	CR
	Body	ATP-02795	O/S CORNER BUMPER	1.00	\$888.98	10.00	\$800.08	Replace	CR
	Body	ATP-02809	FRT O/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	MIS
6012141	VE	ELU-00312	HEADLAMP, BEAM: DIPPED, FOR VOLVO B9TL BUS	1.00	\$445.00	10.00	\$400.50	Replace	MIS
6012142	VE	ELU-00313	HEADLAMP, MAIN BEAM, FOR VOLVO B9TL BUS	1.00	\$372.30	10.00	\$335.07	Replace	? Xan
6012143	VE	ELU-00384	INDICATOR LIGHT: AMBER, FRT, VOLVO B9TL BUS	1.00	\$597.30	10.00	\$537.57	Replace	? Xan
Total					\$6,322.14		\$6,029.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1764.53
1846.00
3610.53
20%
2888.42
45- \$2,900

Ram
4x 600068
3 days
HS
02/11/22 @ 1535
Resay after repair

1764.53

1846