3/20/23, 1:43 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22011024/APA3Q2

Date: 20/03/2023

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2002060330

Claimant Vehicle SJK3074R Insured Vehicle No: XE745Z

No: SJN30/4R Insured Vehicle No. AE/432

Date of Loss: 28/10/2022 Nature of Claim: TP Claim No: 202222007895

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK3074R

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3141330

Reg. Date: 15/10/2008 (Man. Year: 2008) Chassis No: JTDER12W903000791

Colour: White Odometer: 331986 km

Engine Capacity: Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

1794 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|---------------------|------------|------------|--------|
| Parts | 2,676.82 | 737.20 | 1,939.62 | 72.46 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,430.00 | 330.00 | 1,100.00 | 76.92 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,106.82 | 1,067.20 | 3,039.62 | 74.01 |
| Approved Total (Overridden) (S\$) | | 850.00 | | |
| (S\$) | 4,106.82 | 850.00 | 3,256.82 | 79.30 |
| + GST 8.00/8.00% (S\$) | 328.55 | 68.00 | 260.55 | 79.30 |
| Nett Amount (S\$) | 4,435.37 | 918.00 | 3,517.37 | 79.30 |
| + Loss of Use (2.0 x S | \$80.00/day) (S\$) | 160.00 | | |
| + Doc/ | Search Fee (S\$) | 2.00 | | |
| N | ett Liability (S\$) | 1,080.00 | | |

INSPECTION

Date of Assignment: 03/11/2022

SM Automotive (HQ)

Date Inspected: 24/11/2022 Inspected At: 756 JURONG WEST STREET 74, #12-60

Singapore 640756

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2023)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK3074R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|--|-------------------|-------------|------------|
| 1 | 1 | | *RH FRONT DOOR | Not Necessary | 1,277.90 FL | *- FL |
| 2 | 1 | | *RH FRONT DOOR MIRROR | Damaged | 358.20 FL | *358.20 FL |
| 3 | 1 | | *RH FRONT DOOR MIRROR COVER | Cracked | 91.40 FL | *91.40 FL |
| 4 | 1 | | *RH FRONT DOOR BLACK STICKER | Not Necessary | 129.60 FL | *- FL |
| 5 | 1 | | *RH FRONT DOOR GLASS OUTER MOULDING | Not Necessary | 142.60 FL | *- FL |
| 6 | 1 | | *RH FRONT FENDER | Not Necessary | 689.40 FL | *- FL |
| 7 | 1 | | *RH FRONT DOOR GLASS VISOR | Not Necessary | 60.00 FS | *- FS |
| 8 | 1 | | *LH FRONT RIM | Cut | 600.00 FS | *400.00 FS |
| F=Fra | anchise | part. S=SpcN | lett. L=ListItemDisc. | _ | | |
| | | | | Sub Total (S\$) | 3,349.10 | 849.60 |
| | | | - List Item Discount on L Items 25.00/25.00% (S\$) | | | 112.40 |
| | | | | Total Parts (S\$) | 2,676.82 | 737.20 |
| | | | | | | |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|--|------------|------------|--------|
| <u>Lab</u> | our Items | | | |
| 1 | LABOUR FOR PANEL BEATING | New | 500.00 | 200.00 |
| 2 | LABOUR FOR SPRAYPAINTING | New | 500.00 | 100.00 |
| 3 | LABOUR FOR REMOVE /RENEW & TRANSFER RH FRONT DOORS FITTING | New | 200.00 | 0.00 |
| 4 | WIRING CHECK | New | 80.00 | 30.00 |
| 5 | TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS | New | 150.00 | 0.00 |
| | Gross Labour Cost (S\$) | | 1,430.00 | 330.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >