

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 28/10/2022

Estimated repair cost for vehicle no: SJK3074R TOYOTA WISH 1.8 AUTO

CHASSIS: JTDER12W903000791 (2008)

S/N	Qty	Items	U/price	Amount
1	1	RH FRONT DOOR <i>new</i>	\$1,277.90	\$1,277.90 <i>+</i>
2	1	RH FRONT DOOR MIRROR <i>2nd</i>	\$358.20	\$358.20 <i>✓</i>
3	1	RH FRONT DOOR MIRROR COVER <i>cover</i>	\$91.40	\$91.40 <i>✓</i>
4	1	RH FRONT DOOR BLACK STICKER <i>new</i>	\$129.60	\$129.60 <i>+</i>
5	1	RH FRONT DOOR GLASS OUTER MOUDLING <i>new</i>	\$142.60	\$142.60 <i>+</i>
6	1	RH FRONT FENDER <i>new</i>	\$689.40	\$689.40 <i>+</i>

449.60

TOTAL : \$2,689.10

337.20

LESS 25 % \$672.28

SUB-TOTAL : \$2,016.83

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	RH FRONT DOOR GLASS VISOR <i>new</i>	\$60.00	\$60.00 <i>+</i>

RH Front Rem

lit

600
400

TOTAL: \$60.00

TOTAL PARTS: \$2,076.83

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 LABOUR FOR REMOVE / RENEW & TRANSFER RH FRONT DOORS FITTING
- 4 WIRING CHECK
- 5 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS

200
\$500.00

100
\$500.00

330
\$200.00 *+*

30
\$80.00

+
\$150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin

h/s 24/11/22

0284p

Subtotal :- \$1,430.00

Total:- \$3,506.83

Total: 1067.20

h/s: 850 *✓*