



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

03-11-2022

Name: Allianz Insurance Company of Singapore Pte Ltd

Ref Date:

Address: Motor Claims Department

Ref No:

GBG6574K221027

12 Marina View #14-01

Vehicle No:

GBG6574K

Asia Square Tower 2 Singapore 018961

Model / Make:

Nissan NV350 Panel Van

Capacity: 2488 cc

2.5 5AT 5DR Euro V

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front Lh	Head Lamp	\$ 482.00	1	\$ 482.00	N	X
2		Door Side Mirror	\$ 669.90	1	\$ 669.90	N	X
3		Bumper	\$ 993.40	1	\$ 993.40	N	-
4		Bumper Clips 1 set	\$ 48.00	1	\$ 48.00	SN	30 s/N
5		Bumper Bracket	\$ 178.60	1	\$ 178.60	N	✓
6		Step Garnish	\$ 155.00	1	\$ 155.00	N	✓
7		Step Garnish Clips 1 set	\$ 50.00	1	\$ 50.00	SN	20 s/N
8		To check all wiring & electrical component for proper function			\$ 60.00	-	20
9		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 600.00	-	300
10		To putty & spray painting & including touch up paint on accident affected areas			\$ 600.00	-	540
11		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 60.00		11X

Total Parts & Labour of estimate for damaged vehicle

\$ 3,896.90

Total amount in Lumpsum Basis for repaired vehicle



SDL

M/s Liu Bro Auto Engrg Wks

Not Produced
 new
 money
 4/11/22
 1/5# 1400
 3 days.
 wh photo after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 980-50
 102
 855-45
 50
 860
 1765-4
 202
 1412