



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011032/Gqy3m4 Date: 06/06/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 5050S	Veh. Inspected	SNF 5716M	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/3093	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	04/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLB200	c.c	1332	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	W1N2476872W073007	Colour	GREY	
Odometer	11459 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50R19	PIRELLI	8 mm	
L/H Front Tyre	235/50R19	PIRELLI	8 mm	
R/H Rear Tyre	235/50R19	PIRELLI	8 mm	
L/H Rear Tyre	235/50R19	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/11/2022	Inspection Date	04/11/2022	
Survey held at	XIN YUN AUTO PTE LTD BLK 8 KAKI BUKIT AVENUE 4 #05-23 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)REGISTRATION DATE: 03 JUN 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	