



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SNF5761S

Modle: MERCEDES GLB200

No	Description	Labour Charges
1	Checking front /rear wiring harness and lighting system for proper function	\$ 200.00
2	Carry up body cavity preservation for affected area \$80 per panel	\$ 560.00
3	Replacing accident damages parts, knock, jack and straighten accident damages area-FRONT	\$ 2,000.00
4	Spray painting for accident affected damaged area -FRONT	\$ 2,000.00
5	Replacing accident damages parts, knock, jack and straighten accident damages area-REAR	\$ 2,000.00
6	Spray painting for accident affected damaged area -REAR	\$ 2,000.00
7	To front condensor and aircon related items	\$ 350.00
8	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 200.00
9	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00
10	Checking central lock system for proper function	\$ 120.00
11	Checking auto door system for proper function	\$ 120.00
12	Removing and installing rear fender internal garnish and trimming to facilitate the necessary repair	\$ 150.00
13	To conduct wheel alignment	\$ 100.00
14	Removing and installing rear window /windscreen glass	\$ 150.00
15	To remove and install rear camera	\$ 80.00
16	Transferring tailgate and rear end wiring harness for proper function	\$ 150.00
17	Water test after accident repair body work	\$ 120.00
18	Paint protection coating for accident affected areas - FRONT & REAR	\$ 800.00
19	Carry out diagnosis check including cleaning accident fault code front /rear	\$ 800.00
20	Programming coding for replaced accident module and switch module	\$ 800.00
Total labour :		<u>\$ 12,820.00</u>