

利民达摩多
Jementah Motor Works

Blk 14 Defu Lane 10 #01-406
 Singapore 539195
 H/P : 9299 6636 Fax : 6205 7054



not Allowed
 10/11/22
 1/s #2800
 3 days

Date : 09-Nov-22

Qty	Description	Estimated repair cost of GBC 6702 D ISUZU PICK UP	Amt S(\$)
<u>List Items</u>			
1	Rear tailgate	DD 1450	\$ 2,300.74 ✓
1	Rear tailgate lock	11	\$ 185.90 X
1	Rear taillamp - L/H	11	\$ 500.77 X
1	Rear end panel	~	\$ 585.00 X
2	Rear bumper	DD/mogul 905	\$ 1,097.90 ✓
1	Rear bumper brackets	R	\$ 210.00 X
1	Rear bumper top step garnish	wogul 405	\$ 470.15 ✓
2	Rear number plate lamps	CRB	\$ 136.00 ✓
			\$ 5,486.46
		Less 15%	\$ 822.97
			\$ 4,663.49
<u>Special Nett Items</u>			
1	Rear number plate	SVC	\$ 50.00 X
1	Rear tailgate "70km/h" sticker	neu	\$ 28.00 10
1	Rear reverse sensor (1 set)	shock	\$ 350.00 200
			\$ 428.00
<u>LABOUR CHARGES</u>			
1	To remove, replaced damaged lamps and check up rear wiring.		\$ 80.00 20
2	To remove and refit rear reverse sensor.		\$ 120.00 40
3	To apply undercoating.		\$ 100.00 30
4	Panel beating.		\$ 1,200.00 400
5	To re-spray painting on the affected areas.		\$ 1,000.00 400
			\$ 2,500.00

LKK Auto Consultants hence notify the Repairer of the following:

Grand Total : \$ 7,591.49